



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 6006G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT LH HEADLAMP	CUT	1,900.00	1,900.00
1	FRONT LH HEADLAMP COVER	SERVICEABLE	60.00	-
1	FRONT LH HEADLAMP TOP PANEL	SERVICEABLE	200.00	-
1	FRONT GRILLE ASSY	CRACKED	720.00	720.00
1	FRONT NO. PLATE GARNISH	NOT NECESSARY	140.00	-
1	FRONT BUMPER	TORN	370.00	370.00
2	FRONT BUMPER PARKING SENSOR @\$170.00	MALFUNCTION (1PC ONLY)	340.00	170.00
1	FRONT BUMPER LH FOG LAMP	SERVICEABLE	140.00	-
1	FRONT BUMPER LH FOG LAMP COVER	SCRATCHED	130.00	130.00
1	FRONT BUMPER CENTRE LOWER GRILLE	SERVICEABLE	110.00	-
1	FRONT BUMPER LH SIDE RETAINER	NECESSARY	40.00	40.00
1	FRONT BUMPER SPONGE	CRACKED	60.00	60.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	220.00	-
10	FRONT BUMPER CLIPS @\$2.00	NECESSARY	20.00	20.00
1	WIPER TANK	SERVICEABLE	60.00	-
1	FRONT LH FENDER	DENTED	580.00	580.00
1	FRONT LH FENDER INNER SHIELD	SERVICEABLE	140.00	-
10	FRONT LH FENDER INNER SHIELD CLIPS @\$2.00	NECESSARY	20.00	20.00
1	FRONT LH WHEEL BEARING	SERVICEABLE	360.00	-
1	FRONT LH WHEEL SPORT RIM	SERVICEABLE	1,100.00	-
1	FRONT LH HEADLAMP LOWER BRACKET	NOT NECESSARY	60.00	-
1	FRONT LH HEADLAMP ECU	NOT NECESSARY	520.00	-
	COST PLUS 10%		729.00	401.00
			8,019.00	4,411.00
	<b><u>LABOUR</u></b>			
	TO SPRAY PAINTING.		880.00	400.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO RESET HEADLAMP SYSTEM.		280.00	100.00
	TO REPAIR DAMAGES.		780.00	400.00

Report Ref No. CS1/SMR22006814/Rqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	OD/TP CASE (INSURER).		11.00	11.00
			2,101.00	911.00
GRAND TOTAL			10,120.00	5,322.00
RECOMMENDED COST OF REPAIRS				5,322.00

Report Ref No. CS1/SMR22006814/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.