

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 Z G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front LH headlamp	Cut	1,900.00 F	*1,900.00 F ✓
2	1		*Front LH headlamp cover	Serviceable	60.00 F	Repair
3	1		*Front LH headlamp top panel	Serviceable	200.00 F	Reuse
4	1		*Front grille assy	Cracked	720.00 F	*720.00 F ✓
5	1		*Front no. plate garnish xnn	Cut	140.00 F	*140.00 F x
6	1		*Front bumper	Torn	370.00 F	*370.00 F ✓
7	1		*Front bumper parking sensor @ \$170.00	Malfunction	340.00 F	*170.00 F ✓
8	1		*Front bumper LH fog lamp	Serviceable	140.00 F	Reuse
9	1		*Front bumper LH fog lamp cover	Scratched	130.00 F	*130.00 F ✓
10	1		*Front bumper centre lower grille	Serviceable	110.00 F	Reuse
11	1		*Front bumper LH side retainer	Necessary	40.00 F	*40.00 F ✓
12	1		*Front bumper sponge	Cracked	60.00 F	*60.00 F ✓
13	1		*Front bumper reinforcement	Serviceable	220.00 F	Reuse
14	10		*Front bumper clips @ \$2.00	Necessary	20.00 F	*20.00 F ✓
15	1		*Wiper tank	Serviceable	60.00 F	Reuse
16	1		*Front LH fender	Dented	580.00 F	*580.00 F ✓
17	1		*Front LH fender inner shield	Serviceable	140.00 F	Reuse
18	10		*Front LH fender inner shield clips @ \$2.00	Necessary	20.00 F	*20.00 F ✓
19	1		*Front LH wheel bearing	Serviceable	360.00 F	Reuse
20	1		*Front LH wheel sport rim	Serviceable	1,100.00 F	Reuse
Supplementary #1						
21	1		*Front LH headlamp lower bracket xnn	Cracked	60.00 F	*60.00 F x
22	1		*Front LH headlamp ECU xnn	Malfunction	520.00 F	*520.00 F x

F=Franchise part.

4010	Sub Total (\$)	7,290.00	4,730.00
+10%	+ Margin on L,N Items 10.00/10.00% (\$)	729.00	473.00
4411	Total Parts (\$)	8,019.00	5,203.00

Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41. Not valid without Reference section.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	880.00	400 500.00
<u>Labour Items</u>				
2	To check wheel alignment	New	150.00	0.00
3	To reset headlamp system	New	280.00	100 150.00
4	To repair damages	New	780.00	400 540.00
Gross Labour Cost (\$\$)			2,090.00	900 1,190.00

Tokio Marine Insurance Singapore Ltd/SKK6006G/13/05/2022 08:41. Not valid without Reference section.

< END OF ESTIMATES >

4411

11

900

5322

P/P-\$5,322/4days