

Vehicle Damage Assessment Report for [SMN4911S]

Estimate Created: 10/10/2022 08:08 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 13/11/2022 14:45 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number	MFL2022D0003865
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Honda	Model	City
Engine Type			
License Plate Number	SMN4911S	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$3700.00 with 6 days for repair

Insurlogic 1 (13/11/2022 14:43)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BOOTLID		1	685.10	-20.00 %	548.08
REAR BOOTLID CITY LOGO		1	40.00	-20.00 %	32.00
REAR BOOTLID RH LOGO		1	48.00	-20.00 %	38.40
REAR BOOTLID EMBLEM LOGO		1	65.00	-20.00 %	52.00
REAR BOOTLID INNER LOCK		1	255.00	-20.00 %	204.00
REAR BOOTLID INNER RUBBER		1	235.00	-20.00 %	188.00
REAR BOOTLID SIDE REFLECTOR		1	333.00	-20.00 %	266.40
REAR TAILLAMP		1	450.00	-20.00 %	360.00
REAR BUMPER		1	464.00	-20.00 %	371.20
REAR BUMPER SIDE BRACKET		1	70.00	-20.00 %	56.00
REAR BUMPER CLIPS		1	40.00	-20.00 %	32.00
SPARE TYRE TOP BOARD		1	170.00	-20.00 %	136.00
END PANEL		1	492.90	-20.00 %	394.32
REAR END PANEL TOP GARNISH		1	215.00	-20.00 %	172.00

Parts Subtotal 2,850.40

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REVERSE SENSOR		1.0	200.00	0.00 %	200.00

Materials Subtotal 200.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
RNR REVERSE SENSOR	RnR	50.00	0.00 %	50.00
RNR CUSHION	RnR	60.00	0.00 %	60.00
CHECK WIRING	RnR	30.00	0.00 %	30.00
TUFF KOTE	RnR	60.00	0.00 %	60.00
REPLACE/REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	700.00	0.00 %	700.00

Paint

Description		Paint Type	Cost	Markup/Disc %	Price
PAINT ACCIDENT AFFECTED AREAS		Full spray	700.00	0.00 %	700.00
Labor Rate	S\$ 50 / Hour			General Labor Subtotal	900.00
				Paint Labor Subtotal	700.00
				Labor Subtotal	1,600.00

Summary

Repair Cost	4,650.40
Discount(20 %)	(950.40)
	3,700.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,700.00