

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

19TH July 2022

Accident date: 17TH JULY 2022
Estimated repair cost for vehicle no: SMN4911S HONDA CITY 1.5A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,077.00 685.10
2	2	Rear Boot Lid Hinges <i>Item</i>	\$158.00	\$316.00 <i>x</i>
3	1	Rear Boot Lid CITY logo		\$40.00 <i>✓</i>
4	1	Rear Boot Lid RH logo		\$48.00 <i>✓</i>
5	1	Rear Boot Lid emble logo		\$65.00 <i>✓</i>
6	1	Rear boot lid center moulding <i>Item</i>		\$215.00 <i>x</i>
7	6	Rear boot lid center moulding clips <i>Item</i>	\$6.50	\$39.00 <i>x</i>
8	1	Rear Boot Lid Number Plate		\$50.00 <i>x</i>
9	2	Rear Boot Lid Number Plate Lamp	\$42.70	\$85.40 <i>x</i>
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$255.00 <i>✓</i>
11	1	Rear boot lid inner rubber <i>Item</i>		\$235.00 <i>✓</i>
12	1	Rear Boot Lid Inner Trim board <i>Item</i>		\$588.00 <i>x</i>
13	2	Rear boot lid side reflector <i>Item</i>	\$355.00	\$710.00 333
14	1	Rear boot lid windscreen seal <i>Item</i>		\$136.20 <i>x</i>
15	2	Rear tail lamp <i>Item</i>	\$458.00	\$916.00 450
16	1	Rear Bumper <i>Dented</i>		\$950.00 464
17	2	Rear Bumper Side Bracket <i>Item</i>	\$155.00	\$310.00 70-
18	8	Rear bumper clips <i>Item</i>	\$5.00	\$40.00
19	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00 200(SN).
20	1	Rear Bumper Reinforcement <i>Item</i>		\$588.00 <i>x</i>
21	1	Rear Bumper towing cover <i>Item</i>		\$68.00 <i>x</i>
22	1	Spare Tyre Panel Top Board <i>TORN</i>		\$170.00 <i>✓</i>
23	1	Rear End Panel <i>Dented</i>		\$492.90 <i>✓</i>
24	1	Rear End Panel Top Garnish <i>Dented</i>		\$215.00 <i>✓</i>
25	2	Rear fender inner trim board <i>Item</i>	\$386.10	\$772.20 <i>x</i>

Subtotal :- \$8,731.70

Labour charges

To remove & re-fix reverse sensor

\$120.00 50.

Remove / refix rear windscreen

\$120.00 *x*

gum

\$50.00 *x*

To remove & refix cushion

\$120.00 60

To check wiring

\$80.00 30

Tuff kote

\$120.00 60

Panel beating

\$800.00 700

Spray painting

\$800.00 700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-

\$2,210.00

Total:-

\$10,941.70

total: 4650.40
1/5: 3.7K
06Days