



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE
HQ TRANSPORT COMMAND
KRANJI CAMP 3
151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA22006817/Rpq2

Date: 01/12/2022

Code: MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 22100	Veh. Inspected	SLM 4044L
Policy No.		Coverage (\$)	0.00
Claim No.	CY 22/MID22100/150722/0026	Excess (\$)	0.00
Assign From		Assign Date	19/07/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFZ28H3500029531	Colour	ORANGE
Odometer	140946 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	YOKOHAMA	6 mm
L/H Front Tyre	195/50 R16	YOKOHAMA	6 mm
R/H Rear Tyre	195/50 R16	YOKOHAMA	6 mm
L/H Rear Tyre	195/50 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2022	Inspection Date	19/07/2022
Survey held at	160 SIN MING DRIVE #05-12		
Repairer	HIAP LEK AUTOMOBILE TRADING		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**