

ASSIGNMENT

5TD4442P

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____


Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value _____

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. 5TD 54442Yr Regn: 215 119

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota priuscc 1798Colour: blue

A/C. Insured / Std / NI / NA

Sp Reading: 189795

T/Radio: Insured / Std / NI / NA

Eng/No _____

C/No 3TDH33Fu903080542Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 6/5/22D.O.I. 6/5/221700Survey held at CDGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos _____

Others _____

TOTAL

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4204148 JC NO.305515003

AS COMFORT TRANSPORTATION PTE LTD
TOMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO.: SHD4442R	MILEAGE
MAKE : TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)06	DATE/TIME IN 05.2022 09:15
YR OF MANU. 02.05.2019	TARGET DATE
CHASSIS CODE JTDKB3FU903080542	COMPLETION DATE/TIME:

OUNT CARD NO.

JOB DESCRIPTION

ccident Date: 06.05.2022
ATURE: 3P 06.05.2022/C

/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip		Exit Pass	
No.: SHD4442R	JU CHINA	Vehicle No.: SHD4442R	
Signature/Date	Name of Service Advisor	Date	
turned to Service Reception upon collection		To be kept by Security Guard	

REPAIR ESTIMATE

VEHICLE NO SHD4442R

MAKE : TOYOTA

MODEL : PRIUS

DOA 06.05.22

INS. CHINA TAIPING

MVA JUMANI

C/S

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ 586.18
HEADALMP ASSY LH	1		\$ 2,637.60
FRT FENDER LH	1		\$ 1,111.93
FRT FENDER EMBLEM LH	1		\$ 86.50
FRT BUMPER CLIPS	10		\$ 22.00
FRT WHEEL CAP LH	1		\$ 189.60
FRT DOOR ASSY LH	1		\$ 1,264.00
FRT BUMPER SIDE RETIANER LH	1		\$ 77.00
SUB TOTAL			\$ 5,974.81
LESS 25%			\$ 1,493.70
DISCOUNTED TOTAL			\$ 4,481.11
FRT DOOR COMFORT LOGO			\$ 75.00
			\$ 75.00
LABOUR CHARGE			
PANEL BEAT			\$ 1,200.00
SPRAYPAINT			\$ 1,200.00
CHECK WIRING			\$ 50.00
TUFF KOTE			\$ 50.00
TRANSFER DOOR PARTS			\$ 120.00
TOTAL LABOUR			\$ 2,620.00
ESTIMATE TOTAL			\$ 7,176.11

(C/S)
 KSC
 DT
 MC
 MC
 SC
 KSC
 MC
 NTC
 1050
 750
 30
 30
 KSC

Thuan
 82235769
 6/5/22 1700
 C/S 4clayswp

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: