

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
Repair
Less 20%Not Authorized
11 May 85700h
Recovery After Pain
6 days

SKC7715D

Toyota Estima 2.4A

List Price

Toyota Less 25%

Parts

Tailgate	1785.80	R 1874.80 ✓
Tailgate Toyota Logo		M 68 ✓
Tailgate Estima emblem		M 88 ✓
Tailgate Aeras emblem		M 85 ✓
Tailgate no plate chrome garnish		Wap 296.90 ✓
Tailgate inner lock		M 378.90 ✓
Tailgate handle cover		M 70 X
Tailgate inner trim board		M 576.90 ✓
Tailgate wiper motor		M 525 X
Tailgate shock absorbers X 2pc @ 275.40 X 2pc		R 550.80 X
Tailgate Rear windscreen moulding		M 122.80 ✓
Rear Bumper	782	R 1041.70 ✓
Rear Bumper reflectors X 2pc @ 77 X 2pc		= 154 M X
Rear Bumper side retainer (outer) X 2pc @ 55.20 X 2pc		= 110.40 M ✓
Rear Bumper side retainer (inner) X 2pc @ 48.30 X 2pc		= 96.60 M ✓
Boot weatherstrip	126.50	M 252 50in ✓
Rear end panel top garnish	272.60	M 325.50 ✓
end panel lock catch		M 60 X
Rear end panel	625.50	R 874.90 ✓
Lock Actuator Electrical Key		M 345 X
Rear fender inner trim board LHS	678.40	R 937.30 ✓

255

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
Repair
less 20%

SKC7715D

Toyota Estima 24A

Special nett items

nett price

Tailgate inner trim board clips (1set)	na	50	—
Rear Bumper clips (1set)	na	50	—
Tailgate Reverse Camera	shen	480	300in
Reverse parking sensors	shen	280	200in
Rear end panel top garnish clips (1set)	na	50	✓
Rear end panel lower garnish clips (1set)	na	50	✓
Rear License plate with holder	na	50	45in
Rear windscreen sealant	na	80	40in
Rear end panel sealant	na	80	30in

Labour charges \$

700

1) To Renew Damaged parts To cut & weld Rear end panel. \$1500
To Repair the Accident Area.

2) To Remove & Refit Rear windscreen \$200

3) To Renew Tailgate Reverse Camera & Reverse parking sensors. To assemble wiring & check for proper functions. \$100

4) To spray paint Tailgate, Rear Bumper, Rear end panel, spare tyre panel and rear fender LHS. \$1200

5) To carry out anti rust treatment on the affected panels of the accident area. \$120

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13124-5

Pg 2