

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SNC3867P***Not Notwithstanding  
Permy B4 paint***LAD2203-023***81607.03*

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**18 JUL 2022****SNC3867P**

JTDKB3FU703091653

201603575K

TOYOTA

PRIUS GEN 4

27/03/2022

**SJY7244S/CHINA**

18/10/2021

**PART**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

**LIST**

\$	Bu	485.60	✓
\$	PM	332.70	✓
\$	SL	22.00	X
\$	B1	374.50	✓
\$	SL	132.60	X
\$	SL	241.90	X
\$	SL	175.10	X
\$	CMA SL	229.90	✓
\$	SL	126.70	X
\$	SL	651.00	X

**TOTAL \$ 2,772.00****25% \$ 693.00****\$ 2,079.00****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
  - 1 REAR SPOILER CLIP
  - 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
  - 1 END PANEL TRIM CLIP

\$	SL	700.00	X
\$	SL	95.00	6000
\$	SL	70.00	X
\$	SL	180.00	X
\$	SL	85.00	X
\$	SL	65.00	X

**TOTAL \$ 1,195.00****TOTAL PARTS \$ 3,274.00****LABOUR***1208.03*

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SNC3867P****LAD2203-023**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *2001*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 *X*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 *X*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *2201*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 *X***TOTAL \$ 7,390.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Over All Total \$ 10,664.00****(PART-BY-PART) Repair Days****25-DAYS***2 days*

Acknowledged by Repairer

Signature:

Date: