



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301387

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/03/2023
Reference CC6/CTI22006837/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 2957B
Insured Veh. PC 6319L
Claim No. SNM22D205271/C02
Policy No. DMB1SNW00012202102
Accident Date 18/07/2022
Inspection Date 19/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22006837/Upa3q2 Date: 09/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6319L	Veh. Inspected	GBE 2957B	
Policy No.	DMB1SNW00012202102	Coverage (\$)	0.00	
Claim No.	SNM22D205271/C02	Excess (\$)	0.00	
Assign From		Assign Date	19/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (A)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1MC2E26Z0005227	Colour	BLACK	
Odometer	194897 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R14	WEST LAKE	6 mm	
L/H Front Tyre	195 R14	WEST LAKE	6 mm	
R/H Rear Tyre	195 R14	WEST LAKE	6 mm	
L/H Rear Tyre	195 R14	WEST LAKE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	18/07/2022	Inspection Date	19/07/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2957B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN	SHATTERED	1,288.20	1,208.98
1	TAILGATE	DENTED	2,116.70	1,998.30
2	TAILGATE INNER STOPPERS @\$21.00	NOT NECESSARY	42.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	287.10	-
1	TAILGATE LOCK ACTUATOR	NOT NECESSARY	355.10	-
1	TAILGATE 'NISSAN' LOGO	NECESSARY	64.90	64.90
1	TAILGATE 'NV 350' EMBLEM	NOT FITTED	110.00	-
1	TAILGATE 'URVAN' EMBLEM	NOT FITTED	55.00	-
1	TAILGATE INNER TRIM	NOT NECESSARY	217.80	-
1	TAILGATE RUBBER	NOT NECESSARY	134.40	-
1	TAILGATE OUTER CHROME MOULDING	CRACKED	482.30	482.30
1	REAR BUMPER	DENTED / DEFORMED	667.20	667.20
2	REAR BUMPER SIDE RETAINERS @\$27.00	NOT NECESSARY	54.00	-
2	REAR BUMPER SIDE HOLDERS @\$28.00	NOT NECESSARY	56.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	247.10	-
1	REAR END PANEL INNER	NOT NECESSARY	1,110.20	-
1	REAR END PANEL TOP PLATE	NOT NECESSARY	122.80	-
1	REAR STEP PANEL	NOT NECESSARY	178.90	-
2	TAILLAMPS @\$224.80	CRACKED	449.60	449.60
2	TAILLAMP HOUSING PANELS @\$408.00	TO REPAIR SEE LABOUR	916.00	-
1	REAR FENDER	NOT NECESSARY	2,915.00	-
	LESS 10% DISCOUNT		-1,187.03	-487.13
			10,683.27	4,384.15
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	SET TAILGATE INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00

Report Ref No. CC6/CTI22006837/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
			550.00	140.00
	LABOUR			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		100.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND TAILLAMP HOUSING PANELS.		1,500.00	300.00
	TO PUTTY & SPRAY PAINTING.		1,580.00	400.00
			3,560.00	980.00
GRAND TOTAL			14,793.27	5,504.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CC6/CTI22006837/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 2957B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 2957B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 2957B

RE-INSPECTION

