

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 02 Nov 2022

Preliminary Advice

Insured : SJS8796R
Vehicle No
TP Vehicle : SKP5786T
No
Accident Date : 16/07/2022
Make : TOYOTA COROLLA ALTIS
Assignment Date : 19/07/2022
Date of : 20/07/2022
Inspection Est. Duration of : 4
Repair
Inspection At : FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)
176 SIN MING DRIVE #01-06, SIN MING AUTOCARE
SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,943.50
Revised Amount	:S\$	2,579.50
Check Items (Estimated)	:S\$	81.75
Total	:S\$	2,661.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.