

ASS. REC. BY: Tough

REF: CS/CT/2200 6841/Tcy3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9130K
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SJZ7683C Yr Regn: 2020, Oct.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Audi A2 c.c. 999
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 43002 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WU4ZZZ GAIL * A023329
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/45 R18
R: 1
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front
R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. _____
Survey held at SEW
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
Rear
R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 21/7/22
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Rep. Format: _____
Lump Sum / L.B.R. (P) _____

Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS. SI _____
Photos _____
Others _____
TOTAL _____

J.E.W Motor Pte Ltd

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SJZ 7683C

Made : Audi

Model : Q2

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 1,117.00	\$ <i>de</i> 1,117.00
2	Front Bumper Fixing Parts	1	\$ 361.00	\$ <i>x</i> 361.00
3	Front Bumper Grille - Centre	1	\$ 220.00	\$ <i>x</i> 220.00
4	Front Bumper Air Guide Grille RH	1	\$ 189.00	\$ <i>x</i> 189.00
5	Front Bumper Air Guide Grille LH	1	\$ 189.00	\$ <i>x</i> 189.00
6	Front Bumper End Cap RH	1	\$ 66.00	\$ <i>x</i> 66.00
7	Front Bumper Spoiler	1	\$ 332.00	\$ <i>x</i> 332.00
8	Front Bumper Closing Element	1	\$ 174.00	\$ <i>x</i> 174.00
9	Front Wheel Spoiler RH	1	\$ 38.00	\$ <i>x</i> 38.00
10	Front Wheel Spoiler LH	1	\$ 38.00	\$ <i>x</i> 38.00
11	Front Bumper Adapter RH	1	\$ 48.00	\$ <i>x</i> 48.00
12	Front Bumper Adapter LH	1	\$ 48.00	\$ <i>x</i> 48.00
13	Radiator Grille Assembly	1	\$ 1,561.00	\$ <i>crq</i> 1,561.00
14	Radiator Grille Striker Plate	1	\$ 138.00	\$ <i>x</i> 138.00
15	Front Bumper Foam Filler Piece	1	\$ 87.00	\$ <i>cuq</i> 87.00
16	Front Bumper Reinforcement Beam	1	\$ 769.00	\$ <i>pt</i> 769.00
17	Front Bumper Guide Section RH	1	\$ 40.00	\$ <i>x</i> 40.00
18	Front Bumper Guide Section LH	1	\$ 40.00	\$ <i>x</i> 40.00
19	Front Bumper Top Cover	1	\$ 112.00	\$ <i>x</i> 112.00
20	Caution Sticker	1	\$ 16.00	\$ <i>x</i> 16.00
21	Air Cond Sticker	1	\$ 9.00	\$ <i>x</i> 9.00
22	Front Headlamp Mounting RH	1	\$ 132.00	\$ <i>cuq</i> 132.00
23	Front Headlamp Assembly RH	1	\$ 5,245.00	\$ <i>cuq</i> 5,245.00
24	Front Headlamp Mounting LH	1	\$ 132.00	\$ <i>x</i> 132.00
25	Front Headlamp Assembly LH	1	\$ 5,245.00	\$ <i>x</i> 5,245.00
26	Lift Cylinder RH	1	\$ 156.00	\$ <i>x</i> 156.00
27	Lift Cylinder LH	1	\$ 156.00	\$ <i>x</i> 156.00
28	Lift Cylinder Hose RH	1	\$ 204.00	\$ <i>x</i> 204.00
29	Lift Cylinder Hose LH	1	\$ 204.00	\$ <i>x</i> 204.00
30	Radiator Air Guide RH	1	\$ 35.00	\$ <i>x</i> 35.00
31	Radiator Air Guide LH	1	\$ 35.00	\$ <i>x</i> 35.00
32	Radiator Seal RH Outer	1	\$ 8.00	\$ <i>x</i> 8.00

33	Radiator Seal LH Outer	1	\$	8.00	\$ X	8.00
34	Radiator Air Guide Upper Centre	1	\$	25.00	\$ de ✓	25.00
35	Front Bonnet	1	\$	2,940.00	\$ H ✓	2,940.00
36	Front Support Panel	1	\$	1,101.00	\$ Qu ✓	1,101.00
37	Aircon Condenser	1	\$	604.50	\$ X	604.50
38	Radiator Outer	1	\$	1,061.00	\$ X	1,061.00
39	Radiator Inner	1	\$	958.00	\$ X	958.00
40	Front Fender Wheel Arch Garnish RH	1	\$	360.00	\$ de ✓	360.00
41	Front Fender Wheel Arch Garnish LH	1	\$	360.00	\$ X	360.00

Parts Sub Total : \$ 24,561.50

5% Discount \$ 1,228.08

PARTS TOTAL : \$ 23,333.43

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 30.00 ✓ 50.00
3	Front Bumper Grille Centre Clips - Set	1	\$ 30.00	\$ X ✓ 30.00
4	Front Bumper Air Guide Grille Clips - Set	1	\$ 30.00	\$ X ✓ 30.00
5	Radiator Grille Assembly Clips - Set	1	\$ 50.00	\$ 30.00 ✓ 50.00
6	Front Bonnet Insulator Clips - Set	1	\$ 50.00	\$ X ✓ 50.00
7	Front Fender Wheel Arch Garnish Clips - Set	1	\$ 60.00	\$ 10.00 ✓ 60.00
8	Front Bonnet Sealant	1	\$ 150.00	\$ X 150.00
9	Front Fender Sealant	2	\$ 150.00	\$ X 300.00
10	Radiator Coolant	1	\$ 120.00	\$ X 120.00

SPECIAL NETT TOTAL : \$ 890.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 600.00 1,600.00
2	To Spray Paint Affected Areas	\$ 500.00 1,200.00
3	Wiring & Bulb Check	\$ 30.00 100.00
4	To apply anti rust on affected parts	\$ 30.00 120.00
5	To Remove & Refix Aircon Condenser & Top Up Gas	\$ 100.00 150.00
6	To Remove & Refix Radiator & Conduct Pressure Test	\$ X ✓ 150.00
7	To Remove & Refix Front Headlamp Control Unit and Power Module	\$ 30.00 250.00
8	To Conduct Water Leak Test	\$ X 100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 150.00 ✓ 480.00

LABOUR TOTAL : \$ 4,150.00

PARTS TOTAL : \$ 23,333.43

SPECIAL NETT TOTAL : \$ 890.00

LABOUR TOTAL : \$ 4,150.00

GRAND TOTAL : \$ 28,373.43

Taufik 97495749
 WP 21/2/22 @ 1520
 L/S Resurvey after repair
 Taufik@khantaw.com
 05 days

Lik Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		762F
Vehicle Details		
Vehicle No.:		SJZ7683C
Vehicle to be Exported:		Yes
Intended Deregistration Date:		19 Jul 2022
Vehicle Make:		AUDI
Vehicle Model:		Q2 1.0 TFSI S TRONIC
Primary Colour:		Grey
Manufacturing Year:		2019
Engine No.:		CHZC38159
Chassis No.:		WAUZZZGA1LA023329
Maximum Power Output:		85.0 kW (113 bhp)
Open Market Value:		\$23,863.00
Original Registration Date:		27 Oct 2020
First Registration Date:		27 Oct 2020
Transfer Count:		0
Actual ARF Paid:		\$25,409.00
Intended PARF Rebate Details		
PARF Eligibility:		Yes
PARF Eligibility Expiry Date:		26 Oct 2030
PARF Rebate Amount:		\$19,056.00
Intended COE Rebate Details		
COE Expiry Date:		26 Oct 2030
COE Category:		A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):		10
QP Paid:		\$36,534.00
COE Rebate Amount:		\$29,227.00
Total Rebate Amount:		\$48,283.00

The information contained herein is correct as at 18 Jul 2022

OK