

ASS. REC. BY: T. J. J. J.REF: CS/CT/2200 6841/Tcy3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9130K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJZ7683C Yr Regn: 2020, Oct.Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Indi 22 c.c. 999Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 43002 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WU4ZZZGVAL-A023329Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 225/45R18R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 2/7/22Survey held at SEWDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>24/3/23</u>	<u>Finalised LS \$12,500f; 5 days with lve. (Red 15,873.43, 56%)</u>

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final ReportDays Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: TPLump Sum / L.B. (\$ \$12,500f)

J.E.W Motor Pte Ltd

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SJZ 7683C

Made : Audi

Model : Q2

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 1,117.00	\$ de 1,117.00
2	Front Bumper Fixing Parts	1	\$ 361.00	\$ X 361.00
3	Front Bumper Grille - Centre	1	\$ 220.00	\$ X 220.00
4	Front Bumper Air Guide Grille RH	1	\$ 189.00	\$ X 189.00
5	Front Bumper Air Guide Grille LH	1	\$ 189.00	\$ X 189.00
6	Front Bumper End Cap RH	1	\$ 66.00	\$ X 66.00
7	Front Bumper Spoiler	1	\$ 332.00	\$ X 332.00
8	Front Bumper Closing Element	1	\$ 174.00	\$ X 174.00
9	Front Wheel Spoiler RH	1	\$ 38.00	\$ X 38.00
10	Front Wheel Spoiler LH	1	\$ 38.00	\$ X 38.00
11	Front Bumper Adapter RH	1	\$ 48.00	\$ X 48.00
12	Front Bumper Adapter LH	1	\$ 48.00	\$ X 48.00
13	Radiator Grille Assembly 1128.80	1	\$ 1,561.00	\$ crq 1,561.00
14	Radiator Grille Striker Plate	1	\$ 138.00	\$ X nn 138.00
15	Front Bumper Foam Filler Piece	1	\$ 87.00	\$ cuq 87.00
16	Front Bumper Reinforcement Beam 578.40	1	\$ 769.00	\$ bt 769.00
17	Front Bumper Guide Section RH	1	\$ 40.00	\$ X 40.00
18	Front Bumper Guide Section LH	1	\$ 40.00	\$ X 40.00
19	Front Bumper Top Cover	1	\$ 112.00	\$ X nn 112.00
20	Caution Sticker	1	\$ 16.00	\$ X 16.00
21	Air Cond Sticker	1	\$ 9.00	\$ X 9.00
22	Front Headlamp Mounting RH	1	\$ 132.00	\$ ara 132.00
23	Front Headlamp Assembly RH 4124.68	1	\$ 5,245.00	\$ ara 5,245.00
24	Front Headlamp Mounting LH	1	\$ 132.00	\$ X nn 132.00
25	Front Headlamp Assembly LH 4124.68	1	\$ 5,245.00	\$ X nn 5,245.00
26	Lift Cylinder RH	1	\$ 156.00	\$ X 156.00
27	Lift Cylinder LH	1	\$ 156.00	\$ X 156.00
28	Lift Cylinder Hose RH	1	\$ 204.00	\$ X 204.00
29	Lift Cylinder Hose LH	1	\$ 204.00	\$ X 204.00
30	Radiator Air Guide RH	1	\$ 35.00	\$ X 35.00
31	Radiator Air Guide LH	1	\$ 35.00	\$ X 35.00
32	Radiator Seal RH Outer	1	\$ 8.00	\$ X 8.00

33	Radiator Seal LH Outer	1	\$	8.00	\$ X m	8.00
34	Radiator Air Guide Upper Centre	1	\$	25.00	\$ de ✓	25.00
35	Front Bonnet 2231.20	1	\$	2,940.00	\$ H ✓	2,940.00
36	Front Support Panel	1	\$	1,101.00	\$ Qu ✓	1,101.00
37	Aircon Condenser	1	\$	604.50	\$ X m	604.50
38	Radiator Outer	1	\$	1,061.00	\$ X m	1,061.00
39	Radiator Inner	1	\$	958.00	\$ X m	958.00
40	Front Fender Wheel Arch Garnish RH 322	1	\$	360.00	\$ de ✓	360.00
41	Front Fender Wheel Arch Garnish LH	1	\$	360.00	\$ X m	360.00

Parts Sub Total : \$ 24,561.50

5% Discount \$ 1,228.08

PARTS TOTAL : \$ 23,333.43

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X m 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 30.00 ✓ 50.00
3	Front Bumper Grille Centre Clips - Set	1	\$ 30.00	\$ X m 30.00
4	Front Bumper Air Guide Grille Clips - Set	1	\$ 30.00	\$ X m 30.00
5	Radiator Grille Assembly Clips - Set	1	\$ 50.00	\$ 30.00 ✓ 50.00
6	Front Bonnet Insulator Clips - Set	1	\$ 50.00	\$ X m 50.00
7	Front Fender Wheel Arch Garnish Clips - Set	1	\$ 60.00	\$ 10.00 ✓ 60.00
8	Front Bonnet Sealant	1	\$ 150.00	\$ X m 150.00
9	Front Fender Sealant	2	\$ 150.00	\$ X m 300.00
10	Radiator Coolant	1	\$ 120.00	\$ X m 120.00
SPECIAL NETT TOTAL :				\$ 890.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 600 1,600.00
2	To Spray Paint Affected Areas	\$ 500 1,200.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To apply anti rust on affected parts	\$ 30 120.00
5	To Remove & Refix Aircon Condenser & Top Up Gas	\$ 100 150.00
6	To Remove & Refix Radiator & Conduct Pressure Test	\$ X m 150.00
7	To Remove & Refix Front Headlamp Control Unit and Power Module	\$ 30 250.00
8	To Conduct Water Leak Test	\$ X m 100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 150 480.00
LABOUR TOTAL :		\$ 4,150.00

PARTS TOTAL : \$ 23,333.43

SPECIAL NETT TOTAL : \$ 890.00

LABOUR TOTAL : \$ 4,150.00

GRAND TOTAL : \$ 28,373.43

Lik Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Taufik 97495749
 'UP' 21/2/22 @ 1520
 L/S Resurvey after repair
 taufik@khant.com
 05 days