

IGNITE MOTORS PTE LTD

1 Sin Ming Industrial Estate Sector C
#01-117 SINGAPORE 575636

Vehicle number: SNA8324S
Make & Model: Hyundai Elantra
Chassis number: KMHD841CMJU571927
Year: 2017

Third Party Claim

No.	Description of spare parts	Qty	Unit Price	Amount
1	Bonnet	1		\$ 1,910.20X NN
2	Bonnet lock	1		\$ 129.90X NN
3	Front bumper 498.20	1		\$ 478.50
4	Front bumper clips	1set		\$ 60.00
5	Front bumper centre inner rubber seal	1		\$ 29.70X
6	Front bumper towing cover	1		\$ 29.00X
7	Front bumper LH fog lamp cover	1		\$ 35.60X
8	Front bumper LH fog lamp	1		\$ 278.40X
9	Front bumper lower lip	1		\$ 78.00X NN
10	Front bumper lower stiffner	1		\$ 98.00X
11	Front bumper reinforcement	1		\$ 695.00X
12	Front bumper inner sponge	1		\$ 110.70X
13	Front bumper RH side retainer	1		\$ 34.00X
14	Front bumper LH side retainer	1		\$ 34.00 de NN
15	Front bumper RH bracket	1		\$ 26.00X NN
16	Front bumper LH bracket	1		\$ 26.00
17	Front bumper LH curtain duct	1		\$ 29.40X
18	Front grille	1		\$ 485.60X
19	Front grille clips	1set		\$ 50.00X
20	Front grille emblem	1		\$ 28.70X NN
21	Front grille upper garnish	1		\$ 78.40X
22	RH headlamp assy	1		\$ 1,298.80X
23	RH headlamp lower bracket	1		\$ 27.80X
24	RH headlamp lock clips	1		\$ 4.80X
25	LH headlamp assy 1992.60	1		\$ 1,298.80 out NN
26	LH headlamp lower bracket	1		\$ 27.80X NN
27	LH headlamp lock clips	1		\$ 4.80X NN
28	Front LH fender 456.10	1		\$ 434.80 bt
29	Front LH fender splash shield	1		\$ 85.70X
30	Front LH fender splash shield clips	1set		\$ 50.00X
31	Front LH fender inner bracket	1		\$ 43.80X
32	Support panel	1		\$ 949.30X
33	Support panel upper garnish	1set		\$ 50.00X NN
34	Aircon condenser	1		\$ 745.10X
35	Front air duct	1		\$ 98.20X
36	Front LH sport rim (Original)	1		\$ 1,014.00 out
37	Front LH lower arm	1		\$ 311.50X
38	Front LH shock absorber top mounting	1		\$ 126.90X
39	Front LH shock absorber	1		\$ 398.00X
40	Front LH wheel bearing	1		\$ 451.20X
41	Front LH knuckle arm	1		\$ 405.10X
42	Front LH tie rod end	1		\$ 91.50X NN
43	Front LH drive shaft	1		\$ 783.40X
44	Steering rack and pinion	1		\$ 942.80X
45	Front LH door	1		\$ 1,381.50X
46	Front LH door frame black tape	1		\$ 22.30X
47	Front LH side mirror	1		\$ 638.60X

Parts less 20%
Total

\$ 16,411.60
\$ 3,282.32
\$ 13,129.28

No.	Special Nett Items	Qty	Unit Price	Amount
1	Front LH tyre	1		\$ 550.00 x
2	Brake fluid	1		\$ 60.00 x
3	Radiator coolant	1		\$ 60.00 x
4	Front LH door seal	1		\$ 50.00 x
Total:				\$ 720.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, reinstall, replace and realignment parts. To panel beat, cut/weld and straighten affected panels and areas	\$ 1,400.00 <i>400</i>
2	Putty and spray painting on affected areas and panels	\$ 1,200.00 <i>400</i>
3	Check wiring and lighting system on affected areas	\$ 80.00 <i>30</i>
4	Spray rust chemical coating on repaired and replaced panels and areas	\$ 80.00 <i>30</i>
5	Adjust and test drive wheel alignment system (before and after)	\$ 180.00 <i>80</i>
6	Remove and replace front undercarriage parts to assist repair	\$ 450.00 x
7	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 180.00 x
8	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$ 180.00 x
9	Refocus and adjust headlamps assy	\$ 50.00 <i>30</i>
10	Remove and reinstall front LH door inner parts to new door	\$ 150.00 x
Total:		\$ 3,950.00

Spare Parts:
Special Nett:
Labour:

\$ 13,129.28
\$ 720.00
\$ 3,950.00

Total Amount:

\$ 17,799.28

Tanphn 97495749
WP' 19/7/22 @ 1700
L/S Resurvey after repair
tanphn@lkhauto.com
3-4 days
LS \$2850f

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: