

ASS. REC. BY: Taught

REF:

CS/CT122006850/Try 3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$66k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SN483245 Yr Regn: 2017, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c. 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 103638 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4D841CMJ4 571927

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 19/2/22

Survey held at Ignite Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>26/1/23</u>	<u>Finalised LS \$2850; 3 days with Jo. (Red \$14,949.28, 842)</u>

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Rep. Format: TP

Lump Sum / L.B.R. (F) \$2850

Celine Fong (LKKAUTO)

From: Taufikh (LKKAUTO)
Sent: Thursday, 26 January 2023 7:45 PM
To: SUR; CS A Team
Subject: FW: FINALIZATION - SNA 8324 S ; DOA : 07/07/2022

From: Claims Department <claims@ignitemotors.io>
Sent: Thursday, 26 January 2023 7:44:32 pm (UTC+08:00) Kuala Lumpur, Singapore
To: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; admin@ignitemotors.io <admin@ignitemotors.io>
Subject: Re: FINALIZATION - SNA 8324 S ; DOA : 07/07/2022

WITHOUT PREJUDICE

Dear Celine ,

We accept the finalized amount of LS \$ **2,850/ 3 Days** of repair for Vehicle number: **SNA 8324 S** .
We will follow up with the LOD shortly.

Thank you!

The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document.

Regards,
Jo

On Wed, 18 Jan 2023 at 17:57, Celine Fong (LKKAUTO) <celinefong@lkkauto.com> wrote:

Dear Jo,

“Without Prejudice”

Attached marked estimate for vehicle SNA 8324S.

We will be advising our Principal cost of repair of Lump Sum \$2,850.00 with 3 days of repair, subject to their approval.

Best Regards,

IGNITE MOTORS PTE LTD

1 Sin Ming Industrial Estate Sector C
#01-117 SINGAPORE 575636

Vehicle number: SNA8324S

Third Party Claim

Make & Model: Hyundai Elantra

Chassis number: KMHD841CMJU571927

Year: 2017

No.	Description of spare parts	Qty	Unit Price	Amount
1	Bonnet	1	\$	1,910.20X
2	Bonnet lock	1	\$	129.90X
3	Front bumper 498.20	1	\$	478.50 <i>for</i>
4	Front bumper clips	1set	\$	60.00 <i>for</i>
5	Front bumper centre inner rubber seal	1	\$	29.70X
6	Front bumper towing cover	1	\$	29.00X
7	Front bumper LH fog lamp cover	1	\$	35.60X
8	Front bumper LH fog lamp	1	\$	278.40X
9	Front bumper lower lip	1	\$	78.00X
10	Front bumper lower stiffner	1	\$	98.00X
11	Front bumper reinforcement	1	\$	695.00X
12	Front bumper inner sponge	1	\$	110.70X
13	Front bumper RH side retainer	1	\$	34.00X
14	Front bumper LH side retainer	1	\$	34.00 <i>for</i>
15	Front bumper RH bracket	1	\$	26.00X
16	Front bumper LH bracket	1	\$	26.00 <i>for</i>
17	Front bumper LH curtain duct	1	\$	29.40X
18	Front grille	1	\$	485.60X
19	Front grille clips	1set	\$	50.00X
20	Front grille emblem	1	\$	28.70X
21	Front grille upper garnish	1	\$	78.40X
22	RH headlamp assy	1	\$	1,298.80X
23	RH headlamp lower bracket	1	\$	27.80X
24	RH headlamp lock clips	1	\$	4.80X
25	LH headlamp assy 1992.60	1	\$	1,298.80 <i>for</i>
26	LH headlamp lower bracket	1	\$	27.80X
27	LH headlamp lock clips	1	\$	4.80X
28	Front LH fender 456.10	1	\$	434.80 <i>for</i>
29	Front LH fender splash shield	1	\$	85.70X
30	Front LH fender splash shield clips	1set	\$	50.00X
31	Front LH fender inner bracket	1	\$	43.80X
32	Support panel	1	\$	949.30X
33	Support panel upper garnish	1set	\$	50.00X
34	Aircon condenser	1	\$	745.10X
35	Front air duct	1	\$	98.20X
36	Front LH sport rim (Original)	1	\$	1,014.00 <i>for</i>
37	Front LH lower arm	1	\$	311.50X
38	Front LH shock absorber top mounting	1	\$	126.90X
39	Front LH shock absorber	1	\$	398.00X
40	Front LH wheel bearing	1	\$	451.20X
41	Front LH knuckle arm	1	\$	405.10X
42	Front LH tie rod end	1	\$	91.50X
43	Front LH drive shaft	1	\$	783.40X
44	Steering rack and pinion	1	\$	942.80X
45	Front LH door	1	\$	1,381.50X
46	Front LH door frame black tape	1	\$	22.30X
47	Front LH side mirror	1	\$	638.60X

Parts less 20%
Total

\$ 16,411.60
\$ 3,282.32
\$ 13,129.28

No.	Special Nett Items	Qty	Unit Price	Amount
1	Front LH tyre	1		\$ 550.00X
2	Brake fluid	1		\$ 60.00X
3	Radiator coolant	1		\$ 60.00X
4	Front LH door seal	1		\$ 50.00X
Total:				\$ 720.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, reinstall, replace and realignment parts. To panel beat, cut/weld and straighten affected panels and areas	\$ 1,400.00 400
2	Putty and spray painting on affected areas and panels	\$ 1,200.00 400
3	Check wiring and lighting system on affected areas	\$ 80.00 30
4	Spray rust chemical coating on repaired and replaced panels and areas	\$ 80.00 30
5	Adjust and test drive wheel alignment system (before and after)	\$ 180.00 80
6	Remove and replace front undercarriage parts to assist repair	\$ 450.00 X
7	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 180.00 X
8	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$ 180.00 X
9	Refocus and adjust headlamps assy	\$ 50.00 30
10	Remove and reinstall front LH door inner parts to new door	\$ 150.00 X
Total:		\$ 3,950.00

Spare Parts: \$ 13,129.28
Special Nett: \$ 720.00
Labour: \$ 3,950.00

Total Amount: \$ 17,799.28

Tanphn 97495749
WP' 11/7/22 @ 1700
L/S Resurvey after repair
tanphn & Lkhauto.com
3-4 days
LS \$2850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: