

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

20/07/2022

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date :15/07/2022

Estimated repair cost for vehicle no : SLV4942Y HONDA CIVIC 1.8L 5AT

CHASSIS: JHMFD16309S202238 (2008)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Rehnd</i>	\$631.30	\$631.30 ✓
2	1	RH FRONT BUMPER SIDE RETAINER <i>me</i>	\$52.90	\$52.90 ✓
3	1	RH FRONT FENDER <i>Rehnd</i>	\$450.80	\$450.80 ✓
4	1	RH FRONT FENDER INNER SHIELD <i>foru</i>	\$139.60	\$139.60 ✓
5	1	RH FRONT FENDER MUDFLAP <i>new</i>	\$85.60	\$85.60 ✓
6	1	RH FRONT HEADLAMP <i>Rehnd</i>	\$790.40	\$790.40 ✓
7	1	RH FRONT HEADLAMP LOWER BRACKET <i>new</i>	\$79.90	\$79.90 ✓
8	1	RH FRONT SHOCK ABSORBER <i>Best</i>	\$418.40	\$418.40 ✓
9	1	RH FRONT LOWER ARM <i>Best</i>	\$457.60	\$457.60 ✓
10	1	RH FRONT KUNCKLER ARM <i>Best</i>	\$484.10	\$484.10 ✓
11	1	RH FRONT KUNCKLER ARM BEARING <i>Best</i>	\$194.50	\$194.50 ✓
12	1	RH FRONT WHEEL HUP BEARING <i>Best</i>	\$235.90	\$235.90 ✓
13	1	STEERING RACK & PINION <i>Best</i>	\$2,248.90	\$2,248.90 +
14	1	RH FRONT ABS SENSOR <i>Best</i>	\$357.60	\$357.60 +

TOTAL : \$6,627.50

LESS 20 % \$1,325.50

SUB-TOTAL : \$5,302.00

33855.50

23084.40

SLV4942Y HONDA CIVIC 1.8L 5AT

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>xlu</i>	\$80.00	\$80.00 <i>30</i>
2	1	LH FRONT FENDER INNER SHIELD CLIPS <i>xlu</i>	\$80.00	\$80.00 <i>30</i>
3	1	LH FRONT SPORT RIM <i>cut</i>	\$680.00	\$680.00 <i>480</i>
4	1	LH FRONT TYRE <i>xlu</i>	\$260.00	\$260.00 <i>+</i>
5	1	BODY STICKER NEC	\$800.00	\$800.00 <i>480</i>

TOTAL: \$1,900.00

TOTAL PARTS: \$7,202.00

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,000.00 <i>400</i>
2	LABOUR FOR SPRAYPAINTING	\$1,000.00 <i>400</i>
3	WIRING CHECK	\$120.00 <i>30</i>
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	\$200.00 <i>40</i>
5	LABOUR FOR REMOVE & RENEW RH FRONT UNDERCARRIAGE	\$400.00 <i>220</i>
6	LABOUR FOR PRESS / REMOVE & RENEW RH FRONT WHEEL BEARING	\$120.00 <i>+</i>
7	LABOUR FOR REMOVE & RENEW BODY STICKER	\$150.00 <i>+</i>
8	TO CONDUCT WHEEL ALIGNMENT	\$200.00 <i>80</i>

Subtotal :- \$3,190.00

Total:- \$10,392.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Adrian L
1/s 21/07/22.
05 Days.

total: 5284.40

1/s: A.2K.

A.2K.



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER FIRST NAME	SM	DATE	Jul 21, 2022 1:06:50 PM
LICENSE NO.	SLV 4942 Y		
MILEAGE	165432		
MAKE	CUSTOM	MODEL	HONDA CIVIC (FD)
NOTES			

Front Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

TOTAL TOE
PARTIAL TOE
SET BACK
CAMBER
CASTER
KING-PIN
INCL. ANGLE
Toe-out on turns
STEERING IN
STEERING OUT

min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
-1.00	0.00	1.00			3.00				3.10		
-0.50	0.00	0.50		1.40		1.60		0.00		3.00	
---	---	---			-0°06"				-0°06"		
-1°00"	0°00"	1°00"		-0°10"		-1°26"	1°16"	-0°10"		-1°26"	1°16"
5°30"	6°30"	7°30"		6°14"		5°56"	0°16"	6°14"		5°56"	0°16"
---	---	---		11°56"		8°14"	3°42"	11°56"		8°14"	3°42"
---	---	---		11°46"		6°46"		11°46"		6°46"	
---	---	---		---		---		---		---	
---	---	---		---		---		---		---	
---	---	---		---		---		---		---	

Rear Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

TOTAL TOE
PARTIAL TOE
SET BACK
CAMBER
THRUST ANGLE

min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
0.80	1.80	2.90			3.40				3.40		
0.40	0.90	1.40		2.30		1.10		2.30		1.10	
---	---	---			-0°02"				-0°02"		
-2°00"	-1°00"	0°00"		-1°36"		-2°16"	0°38"	-1°36"		-2°16"	0°38"
-0°08"	0.00	0°08"			0°04"				0°04"		