



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22006854/Dvy3m4	
			Date: 05/01/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5618E	Veh. Inspected	SHB 6381E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/22/2050	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	19/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVLU189886	Colour	BLUE
	Odometer	246612 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/07/2022	Inspection Date	20/07/2022
	Survey held at	BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE		
	Repairer	BIFROST AUTO PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	