

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/072022/5528
Date : 16-07-2022
Accident Date : 16-07-2022

Vehicle Details

Make & Model : Toyota NOAH HYBRID 1.8X CVT
Chassis No : ZWR800509090
Registration No : SNC7378H

Third Party Vehicle Details

Registration No : YQ2549K

S/N	Description	Qty	Amount (\$S)
1	RH HEADLAMP	1.00	200 / \$3,806.30
2	FRONT BUMPER	1.00	Def / \$663.90
3	FRONT BUMPER RH FOG LAMP COVER	1.00	scr / \$113.50
4	FRONT BUMPER RH SIDE RETAINER	1.00	rec / \$103.50
X 5	FRONT BUMPER SPONGE	1.00	^ / \$148.70
X 6	FRONT BUMPER REINFORCEMENT	1.00	^ / \$323.60
7	FRONT BUMPER CLIPS	10.00	rec / \$55.00
8	TAILGATE	1.00	DT / \$1,919.30
9	TAILGATE GLASS LH MOULDING	1.00	rec / \$72.80
10	TAILGATE GLASS RH MOULDING	1.00	rec / \$72.80
11	TAILGATE OUTER CHROME GARNISH	1.00	Br / \$896.60
12	TAILGATE INNER TRIMBOARD	1.00	- cut / \$605.10
13	TAILGATE RUBBER	1.00	^ / \$394.70
14	TAILGATE LOCK	1.00	Scr X / \$495.40
15	LH TAILLAMP	1.00	Cra / \$1,446.80
R 16	LH TAILLAMP PANEL	1.00	r X / \$189.80
17	LH CORNER PANEL	1.00	cut / \$187.50
18	LH CORNER PANEL RETAINER	1.00	rec / \$170.60
19	REAR BUMPER	1.00	Cut / \$573.60
20	REAR BUMPER LH REFLECTOR	1.00	Cra / \$63.40
21	REAR BUMPER TOWING COVER	1.00	Cut / \$22.00
22	REAR BUMPER LH SIDE RETAINER	1.00	rec / \$77.80
X 23	REAR BUMPER KEYLESS SENSOR	1.00	? / \$86.30
24	REAR BUMPER CLIPS	10.00	rec / \$55.00
R 25	REAR END PANEL	1.00	? / \$779.40
26	REAR END PANEL TOP TRIM	1.00	? / \$162.50
27	SPARE TYRE PANEL TOP COVER	1.00	? / \$1,175.40
28	REAR LH FENDER INNER TRIMBOARD	1.00	? / \$658.40
29	REAR LH FENDER RAIL COVER	1.00	DTs / \$442.70
			\$15,562.40

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Discount: -25%

(\$3,890.60)

30	REAR WINDSCREEN GUM	1.00	\$11,671.80
31	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	4000 \$80.00
32	TO RESET HEADLAMP SYSTEM	1.00	120 \$180.00
33	TO REPAIR DAMAGES	1.00	600 \$280.00
34	TO SPRAY PAINTING	1.00	600 \$980.00

Subtotal w/o GST:

\$14,071.80

Thewy @ Lhh auto. lon
82235769
PIP 5 days swp
20/7/22 1715

Issued by Tan Leng Leng

This is a computer-generated document. No signature is required.