

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200228
Date: 18 Jul 2022
Veh Reg No: SJG3341R
Make/Model: CHEVROLET OPTRA
1.6MT MY7.5 FACELIFT
Chasis No: KL1NF196E8H103476
Reg. Date: 26/06/2008
Your Ref No: SNE9477G

Claim Type: Third Party
Accident Date: 15/07/2022
TP Veh Reg No: SNE9477G

Estimate Repair Cost to Vehicle No :SJG3341R

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	1,060.00	✓
2	1 PC BOOT LID LOGO <i>new</i>	67.00	✓
3	1 PC BOOT LID OPTRA EMBLEM	55.00	✓
4	1 PC BOOT LID CHEVROLET EMBLEM <i>new</i>	43.00	✓
5	1 PC BOOT LID VGIS EMBLEM	48.00	✓
6	1 PC BOOT LID MIVEC EMBLEM	38.00	✓
7	2 PCS BOOT LID HINGES <i>new</i>	198.00	✓
8	1 PC BOOT LID RUBBER <i>at</i>	185.00	✓
9	1 PC BOOT LID LOCK <i>Dented</i>	187.00	✓
10	1 PC BOOT LID LOCK CHECKER <i>new</i>	48.00	+
11	1 PC BOOT LID TRIM <i>new</i>	145.00	+
12	1 PC REAR PANEL <i>Dented</i>	576.00	✓
13	1 PC REAR PANEL TRIM <i>Deformed</i>	135.00	✓
14	1 PC SPARE TYRE PANEL <i>Repair</i>	866.00	×
15	1 PC SPARE TYRE HARDBOARD <i>Deformed</i>	289.00	✓
16	1 PC TAIL LAMP RH <i>cut</i>	325.00	✓
17	1 PC TAIL LAMP PANEL RH <i>Repair</i>	166.00	+
18	1 PC REAR FENDER TRIM RH <i>new</i>	165.00	+
19	1 PC TAIL LAMP LH <i>cut</i>	325.00	✓
20	1 PC TAIL LAMP PANEL LH <i>Repair</i>	166.00	+
21	1 PC REAR FENDER TRIM LH <i>new</i>	165.00	+
22	1 PC REAR BUMPER <i>Distorted</i>	1,052.00	✓
23	2 PCS REAR BUMPER BRACKETS <i>new</i>	142.00	+
24	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	68.00	✓
25	1 PC REAR BUMPER REINFORCEMENT <i>Distorted</i>	466.00	305
26	1 PC REAR BUMPER SPOILER <i>Deformed</i>	850.00	650 (SW)
27	1 PC REAR LOWER BUMPER CHROME <i>new</i>	121.00	✓
28	1 PC EXHAUST PIPE <i>new</i>	776.00	×

4879

4391.10

650 (SW)

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2200228
Date: 18 Jul 2022
Veh Reg No: SJG3341R
Make/Model: CHEVROLET OPTRA
 1.6MT MY7.5 FACELIFT
Chasis No: KL1NF196E8H103476
Reg. Date: 26/06/2008
Your Ref No: SNE9477G

Claim Type: Third Party
Accident Date: 15/07/2022
TP Veh Reg No: SNE9477G

Estimate Repair Cost to Vehicle No :SJG3341R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		8,727.00	
	Less 10%	872.70	7,854.30
Special Net			
29	1 SET BOOT LID TRIM CLIPS <i>Mem</i>	60.00 <i>+</i>	
30	1 SET REAR PANEL TRIM CLIPS <i>Mem</i>	40.00 <i>20</i>	
31	1 SET REAR FENDER TRIM CLIPS RH <i>Mem</i>	60.00 <i>+</i>	
32	1 SET REAR FENDER TRIM CLIPS LH <i>Mem</i>	60.00 <i>+</i>	
33	1 SET REAR BUMPER REVERSE SENSORS <i>Day 1</i>	280.00 <i>200</i>	
34	1 SET REAR BUMPER CLIPS <i>Mem</i>	60.00 <i>30</i>	
35	1 PC EXHAUST TAIL CHROME <i>Not cut</i>	180.00 <i>100</i>	
		740.00	740.00
Labour			
36	1 TO REMOVE AND REPLACE THE DAMAGED PARTS. KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 <i>1000</i>	
37	1 TO SPRAY PAINTING	1,000.00 <i>✓</i>	
38	1 TO SPRAY PANEL SEALANT	150.00 <i>60</i>	
39	1 TO REPLACE EXHAUST PIPE	150.00 <i>X</i>	
40	1 TO REPLACE INNER TRIM	150.00 <i>80</i>	
41	1 TO REPLACE REVERSE SENSOR <i>2220</i>	80.00 <i>50</i>	
42	1 TO CHECK WIRING	50.00 <i>30</i>	
		2,780.00	2,780.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200228
Date: 18 Jul 2022
Veh Reg No: SJG3341R
Make/Model: CHEVROLET OPTRA
1.6MT MY7.5 FACELIFT
Chasis No: KL1NF196E8H103476
Reg. Date: 26/06/2008
Your Ref No: SNE9477G

Claim Type: Third Party
Accident Date: 15/07/2022
TP Veh Reg No: SNE9477G

Estimate Repair Cost to Vehicle No :SJG3341R

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 11,374.30
		Add GST @ 7%	796.20
		Total Amount Payable	S\$ 12,170.50

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND ONE HUNDRED SEVENTY AND CENTS FIFTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 18/07/22
JG Pump
OT
Total 7611.10
L/S G.T.K.
(6.1K.)