

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 5368K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	2,159.00	985.00
1	FRONT BUMPER LOWER GARNISH	DEFORMED	598.00	329.00
1	FRONT BUMPER FOGLAMP RH	NOT NECESSARY	359.00	-
1	FRONT BUMPER FOGLAMP CHROME COVER RH	NOT NECESSARY	298.00	-
1	FRONT BUMPER CORNER SUPPORT BRACKET	NOT NECESSARY	128.00	-
1	FRONT BUMPER SIDE COVER RH	NOT NECESSARY	212.00	-
1	FRONT BUMPER SIDE BRACKET RH	NOT NECESSARY	159.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	798.00	-
1	FRONT FENDER WHEEL ARCH RH	CUT	398.00	267.00
1	HEADLAMP RH	CUT	4,159.00	4,159.00
	LESS 10% DISCOUNT		-926.80	-574.00
			8,341.20	5,166.00
	SPECIAL NETT ITEMS			
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	65.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
			125.00	30.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		600.00	400.00
	TUFF COAT.		150.00	30.00
	REALIGN HEADLAMP.	NOT NECESSARY	120.00	-
	WIRING CHECK.		80.00	30.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	650.00	-
			2,200.00	760.00
	GRAND TOTAL		10,666.20	5,956.00

Report Ref No. CS/AGI22006860/Avy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,750.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22006860/Avy3m4



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.