

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
PANDE SHRIKANT DIGAMBARRAO	Cust No/Name	/PANDE SHRIKANT DIGAMBARRAO
17 FLORA ROAD	Reg No/Reg Date	SMT7550Z / 16/07/202
#03-03	Date In/Mileage	/ 0
SINGAPORE 509735	Chassis No	MMBSTA13AKH003987
Contact No Mobile: 91149559	Engine No	3A92UJD2894
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	18/07/2022/ 13:37	TLK	282 / Kevin Leong	25385		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2560.00
REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA							
REPAIR ON FRT RH DOOR							
E PNT98000							2200.00
PAINT WORK ON FRT BUMPER, FRT RH FENDER & FRT RH DOOR							
M SUNDRY							120.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							120.00
PERFORM RUST PREVENTION							
A 54900099							150.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
A 33900099							640.00
REPLACE FRONT UNDERCARRIAGE							
M SUNDRY							50.00
TO TRANSFER FRT RH RIM INCLUDING BALANCING							
B WHEELALIGNMENT120L							180.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							50.00
SUNDRIES							
M HEADLAMP ASSY,RH				1.00	1208.00	00.00	1208.00
M FENDER,FR RH				1.00	639.00	00.00	639.00
M FACE,FR BUMPER				1.00	974.00	00.00	974.00
M BRACKET,FR BUMPER,RH				1.00	16.00	00.00	16.00
M GARNISH,FR BUMPER,RH				1.00	154.00	00.00	154.00
M AIR DAM,SIDE,FR RH				1.00	18.00	00.00	18.00
M SHIELD,FR WHEELHOUSE,RH				1.00	99.00	00.00	99.00
M GARNISH,FR FENDER				1.00	79.00	00.00	79.00
M WHEEL,DISC				1.00	834.00	00.00	834.00
M CROSSMEMBER,FR AXLE,NO.1				1.00	877.00	00.00	877.00
M ARM ASSY,FR SUSP,LWR RH				1.00	283.00	00.00	283.00
M STRUT,FR SUSP				1.00	461.00	00.00	461.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
PANDE SHRIKANT DIGAMBARRAO	Cust No/Name /PANDE SHRIKANT DIGAMBARRAO
17 FLORA ROAD	Reg No/Reg Date SMT7550Z / 16/07/202
#03-03	Date In/Mileage / 0
SINGAPORE 509735	Chassis No MMBSTA13AKH003987
Contact No Mobile: 91149559	Engine No 3A92UJD2894
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	18/07/2022/ 13:37	TLK	282 / Kevin Leong	25385

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GEAR & LINK ASSY,STEERING	1.00	1473.00	00.00	1473.00
Estimate				

Confirm & accepted by

7% GST on	Nett 13465.00	13,465.00
		942.55
Total Payable		14,407.55

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.