

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.  
Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 20 Jul 2022

## **Preliminary Advice**

Vehicle No	: SMZ5167D	Accident Date	: 18/07/2022
Make	: MERCEDES-BENZ A180	Policy No.	: SP2001749151- 01
Assignment Date	: 19/07/2022	Excess	: S\$600.00
Date of Inspection	: 20/07/2022	Est. Duration of Repair	: 11
Inspection At	: CITY AUTO PTE LTD (HQ) 160 SIN MING DRIVE #05-01,, SIN MING AUTOCITY, SINGAPORE 575722		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 27,137.50
Revised Amount	:S\$ 18,521.00
Check Items (Estimated)	:S\$ 2,235.00
Total	:S\$ 20,756.00

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 85,000.00
COE / PARF Rebate	:S\$ 29,332.00
Salvage Value	:S\$

Margin for Repair

:S\$ 55,668.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The vehicle repair on Lump Sum basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.