

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (After-sales)
64756624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62565
Date Estimated : 18/07/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Lee Jiann Yow, Lionel (Li Jianyou)
9 Holland Hill
#03-01
Singapore 278738

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SL300X	WBATS720609C46012	02/09/2020	X3 sDrive20i	12638

DESCRIPTION

To replace bumper rear panel, tailgate. and tail end panel. 850x2

1700 ✓ 4,250.00

To spray paint bumper rear panel, tailgate and tail end panel.

1972 ✓ 2,819.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ✓ 177.00

To replace bootlid smart opener control unit, top and bottom sensor line including program and conduct check for proper function.

627 ✓ 661.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

594 ✓ 531.00

To replace rear exhaust silencer including alignment system and conduct check for leak.

4 ✓ 531.00

To check electrical wiring system and lighting at the rear section for proper function.

168 ✓ 177.00

To carry out body cavity preservation. (Per panel).

112 ✓ 118.00

To carry out body cavity preservation. (For cut panel).

4 ✓ 531.00

To replace rear windscreen glass.

545 ✓ 574.00

To conduct water leak tests.

71 ✓ 75.00

To supply and install rear windscreen solar film.

594 ✓ 531.00

Sundries.

7 ✓ 150.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62565
Date Estimated : 18/07/2022
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SL300X	WBATS720609C46012	02/09/2020	X3 sDrive20i	12638

Total Labour 1: 11,125.00

DESCRIPTION	QTY	PRIC	VALUE
REAR SILENCER <i>7</i> X NN	1	1,373.70	1,373.70
TAIL PANEL <i>7</i> X NN	1	542.20	542.20
INTERIOR TAIL TRIM PANEL <i>7</i> X NN	1	473.90	473.90
TRUNK LID <i>7</i> X NN	1	2,051.00	2,051.00
REAR BUMPER CARRIER <i>7</i> X NN	1	776.85	776.85
LH SIDE GUIDE FOR BUMPER <i>7</i> X NN	1	136.30	136.30
LH BUMPER GUIDE <i>7</i> X NN	1	163.55	163.55
RH BUMPER GUIDE <i>7</i> X NN	1	163.55	163.55
REAR BUMPER TOWING LUG COVER (M) <i>7</i> X NN	1	77.30	77.30
REAR BUMPER PANEL PRIMED (M/PMA) <i>7</i> X NN	1	1,562.95	1,562.95
SET MOUNTING PDC/PMA SENSOR REAR(M) <i>7</i> X NN	1	128.65	128.65
REAR BUMPER BOTTOM TRIM PANEL (M) <i>7</i> BR	1	372.15	372.15
LOCK TRUNK LID <i>7</i> X NN	1	230.30	230.30
TRUNK LID POWER LOCK PANEL <i>7</i> X NN	1	246.55	246.55
SPRING SUPPORT FOR VIBRATION ABSORB <i>7</i> X NN	1	320.40	320.40
RH SPINDLE DRIVE <i>7</i> X NN	1	490.55	490.55
BUMP STOP <i>7</i> X NN	10	3.30	33.00
REAR WINDOW GREEN <i>7</i> X NN	1	1,075.05	1,075.05
TRUNK LID GASKET <i>7</i> X NN	1	152.00	152.00
SET ADHESIVE PADS FOR ACE 2.0 <i>7</i> X NN	1	37.35	37.35
(DG) CLEANER R1 (100ML) <i>7</i> n/c	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>7</i> n/c	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>7</i> n/c	1	27.85	27.85

Total Parts : 10,724.40

Steve (LKK)
15/8/22 12.00p
PIP
Mj P/L
S Lys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



22,648.21

Labour 1	:	11,125.00
Parts	:	10,724.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,529.46
Grand Total	:	23,378.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **