

Performance Motors

BMW Dealer



Final Report

Estimate No. : **b1 62565**
Date Estimated : **18/07/2022**
Prepared By : **Foong Shiuh Jye**

Page No. :

- ESTIMATE REPAIR FOR -

Lee Jiann Yow, Lionel (Li Jianyou)
9 Holland Hill
#03-01

Singapore 278738

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SL300X	WBATS720609C46012	02/09/2020	X3 sDrive20i	20569

DESCRIPTION	ORIGINAL PRICE		NETT
To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	1,700.00	0.00	1,700.00
To spray paint rear bumper and boot lid	1,972.00	0.00	1,972.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To replace boot lid smart opener top sensor line include programming and conducting checks for proper function	627.00	0.00	627.00
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00	0.00	504.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
To replace rear windscreen glass.	574.00	0.00	574.00
To conduct water leak tests.	75.00	0.00	75.00
Sundries.	150.00	0.00	150.00

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W



Performance Motors

BMW Dealer



Final Report

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	4.00	0.00	10.80
# 3M S/F CRYSTALLINE REAR WINDSCREEN	420.56	1.00	0.00	420.56
TRUNK LID	2,051.00	1.00	0.00	2,051.00
# REAR BUMPER BOTTOM REINFORCEMENT	81.50	1.00	0.00	81.50
REAR BUMPER PANEL PRIMED (M/PMA)	1,562.95	1.00	0.00	1,562.95
REAR BUMPER BOTTOM TRIM PANEL (M)	372.15	1.00	0.00	372.15
# EMBLEM GROMMET	0.95	2.00	0.00	1.90
# PLAQUE 82MM	72.85	1.00	0.00	72.85
# LETTERING X3	65.60	1.00	0.00	65.60
# LETTERING S DRIVE 20I	98.35	1.00	0.00	98.35
REAR WINDOW GREEN	1,075.05	1.00	0.00	1,075.05
# SENSOR WIRE FOR SMART OPENER TOP	47.25	1.00	0.00	47.25
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	27.85	1.00	0.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	6,050.00
Total Parts :	6,177.06
Total Labour & Parts :	12,227.06
Deduction for Excess :	
Total Repair Costs less Excess:	12,227.06
GST @7%:	855.89
Grand Total :	13,082.95

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

