

Steve

CC4/ AIS 2200 6872/993

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SND 6878H Yr Regn: 31/5/22
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes-Benz E200 c.c. 1991
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading 3122 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WIK 2130802 BPS404
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/55R17
 R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or . _____

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 17/7/22 D.O.I. 26/7/22
 Survey held at Cycle & Carriage
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV- 266K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Repair Format: _____

Lump Sum / I.B.R. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SND6878H

Allianz Insurance Singapore Pte.
Ltd
79 Robinson Road #09-01
Singapore 068897

Vehicle & Document Information

WIP No 58330
Reg No/Reg Date SND6878H / 31/05/2022
Date In/Mileage / 0
Chassis No W1K2130802B0544049
Engine No 26492030493335
Make/Model MB/E 200 SEDAN
Colour/Trim 028 831 Graphite Gr/ 042 201 Leather B1a

Account No	Terms	Date/Time Printed	CSE	Operator			
CTP00001	Cash	18/07/2022/ 16:41	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPN SUN

POLICY NO/ACC DATE : 7220059238 // 17-07-2022
DRIVE IN: 18-07-2022 // TP CAR NO: GBJ3555U (ALLIANZ INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER &
REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER

M LH/F HEADLAMP

M LH/F HEADLAMP CONTROL UNIT

M LH/F FENDER

M LH/F INTERMEDIATE LAYER

M FRT BUMPER

M LH/F BUMPER BRACKET

M LH/F BASIC CARRIER FOR BUMPER

M CT/F BASIC CARRIER FOR BUMPER

M FRT IMPACT ABSORBER

M BONNET

M BONNET LEFT UPPER CATCH

M BONNET LEFT LOWER CATCH

M FRT CROSS MEMBER

M FRT END SUPPORT MEMBER

0.10 380.00

120.00

2400.00

1920

0.02 2800.00

1.00 3619.80 00.00 3619.80

1.00 701.13 00.00 701.13

1.00 1073.57 00.00 1073.57

1.00 12.38 00.00 12.38

1.00 1637.77 00.00 1637.77

1.00 18.16 00.00 18.16

1.00 70.40 00.00 70.40

1.00 117.33 00.00 117.33

1.00 203.34 00.00 203.34

1.00 2465.78 00.00 2465.78

1.00 38.26 00.00 38.26

1.00 72.19 00.00 72.19

1.00 573.71 00.00 573.71

1.00 982.38 00.00 982.38

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before/after spray painting

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also pay the full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

STEP (LKK)
26/7/22, 10.00
M R
P/P

Nett 17,286.20
7% GST on 17286.20 1210.03

Total Payable 18,496.23

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg