



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SND6878H

Allianz Insurance Singapore Pte.
Ltd
79 Robinson Road #09-01
Singapore 068897

Vehicle & Document Information

WIP No **58330**
Reg No/Reg Date **SND6878H / 31/05/2022**
Date In/Mileage **/ 0**
Chassis No **W1K2130802B0544049**
Engine No **26492030493335**
Make/Model **MB/E 200 SEDAN**
Colour/Trim **028 831 Graphite Gr/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	18/07/2022/ 16:41	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 7220059238 // 17-07-2022 DRIVE IN: 18-07-2022 // TP CAR NO: GB03555U (ALLIANZ INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				2400.00
A BPIRES RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER			0.02	2800.00
M LH/F HEADLAMP	1.00	3619.80	00.00	3619.80
M LH/F HEADLAMP CONTROL UNIT	1.00	701.13	00.00	701.13
M LH/F FENDER	1.00	1073.57	00.00	1073.57
M LH/F INTERMEDIATE LAYER	1.00	12.38	00.00	12.38
M FRT BUMPER	1.00	1637.77	00.00	1637.77
M LH/F BUMPER BRACKET	1.00	18.16	00.00	18.16
M LH/F BASIC CARRIER FOR BUMPER	1.00	70.40	00.00	70.40
M CT/F BASIC CARRIER FOR BUMPER	1.00	117.33	00.00	117.33
M FRT IMPACT ABSORBER	1.00	203.34	00.00	203.34
M BONNET	1.00	2465.78	00.00	2465.78
M BONNET LEFT UPPER CATCH	1.00	38.26	00.00	38.26
M BONNET LEFT LOWER CATCH	1.00	72.19	00.00	72.19
M FRT CROSS MEMBER	1.00	573.71	00.00	573.71
M FRT END SUPPORT MEMBER	1.00	982.38	00.00	982.38

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **17,286.20**
7% GST on **17286.20** **1210.03**

Authorized signatory and company stamp

Total Payable 18,496.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg