



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 6500111 X

ESTIMATE FOR SND6878H

Allianz Insurance Singapore Pte.
Ltd
79 Robinson Road #09-01
Singapore 068897

Vehicle & Document Information
WIP No 58330
Reg No/Reg Date SND6878H / 31/05/2022
Date In/Mileage / 0
Chassis No W1K2130802B0544049
Engine No 26492030493335 *0d- 3122*
Make/Model MB/E 200 SEDAN
Colour/Trim 028 831 Graphite Gr/ 042 201 Leather Bla

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|-------|-------------------|-----|------------------------|
| CTP00001 | Cash | 18/07/2022/ 16:41 | AQ | 305 / Alan Quek A1 Lun |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

M BPNUN

POLICY NO/ACC DATE : 7220059238 // 17-07-2022
DRIVE IN: 18-07-2022 // TP CAR NO: GB035550 (ALLIANZ INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER &
REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER

M LH/F HEADLAMP

M LH/F HEADLAMP CONTROL UNIT

M LH/F FENDER

M LH/F INTERMEDIATE LAYER

M FRT BUMPER

M LH/F BUMPER BRACKET

M LH/F BASIC CARRIER FOR BUMPER

M CT/F BASIC CARRIER FOR BUMPER

M FRT IMPACT ABSORBER

M BONNET

M BONNET LEFT UPPER CATCH

M BONNET LEFT LOWER CATCH

M FRT CROSS MEMBER

M FRT END SUPPORT MEMBER

0.10

380.00

120.00

2400.00

1920

0.02

2800.00

2400.00

1.00

3619.80

1.00

701.13

1.00

1073.57

1.00

12.38

1.00

1637.77

1.00

18.16

1.00

70.40

1.00

117.33

1.00

203.34

1.00

2465.78

1.00

38.26

1.00

72.19

1.00

573.71

1.00

982.38

982.38

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before/after spray painting

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of issue. This is a computer generated document, no signature is required.
Estimated costs quoted are on a Windscreen Repair Basis. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also pay for the removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Nett 17,286.20
7% GST on 17286.20 1210.03

Total Payable 18,496.23

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 1 of 1



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SND6878H

Allianz Insurance Singapore Pte.
Ltd
79 Robinson Road #09-01
Singapore 068897

Vehicle & Document Information

WIP No **58330**
Reg No/Reg Date **SND6878H / 31/05/2022**
Date In/Mileage **26/07/2022 / 3122**
Chassis No **W1K2130802B0544049**
Engine No **26492030493335**
Make/Model **MB/E 200 SEDAN**
Colour/Trim **028 831 Graphite Gr/ 042 201 Leather Bla**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|-------|-------------------|-----|------------------------|
| CTP00001 | Cash | 26/08/2022/ 18:39 | AQ | 305 / Alan Quek Ai Lun |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

M_BPNSUN

POLICY NO/ACC DATE : 7220059238 // 17-07-2022
DRIVE IN: 18-07-2022 // TP CAR NO: GBJ3555U (ALLIANZ INSURANCE)
DATE IN/DATE SURVEY: 26-07-2022 // LKK STEVE
BY/AUTHORIZED ON : LKK CECILIA CHONG // 26-07-2022

X COMBINATION NUT
X FUSE LINK

4.00 4.05 00.00
2.00 5.18 00.00

NEC 16.20 ✓
NEC 10.36 ✓

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 26.56**
1.86

Authorized signatory and company stamp

Total Payable 28.42

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg