

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006875/UQY3M4**Date:** 03/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00042802201	
Claimant Vehicle No :	SJD9787P	Insured Vehicle No :	SMS211D	
Date of Loss:	18/07/2022	Nature of Claim:	TP	Claim No: SNM22D205001/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD9787P		Engine No:	K20A5822326
Make & Model:	HONDA CIVIC, 2.0 TYPE-R (M)		Chassis No:	FD21402246
Reg. Date:	11/04/2008 (Man. Year: 2008)		Odometer:	383546 km
Colour:	White			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 ZR17	Rear Tyre Size:	225/45 ZR17
Front Left Side:	Habilead 7 mm	Rear Left Side:	Habilead 7 mm
Front Right Side:	Habilead 7 mm	Rear Right Side:	Habilead 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,172.72	2,099.20	1,073.52	33.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,430.00	620.00	30.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,222.72	3,529.20	1,693.52	32.43
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	5,222.72	2,800.00	2,422.72	46.39
+ GST 7.00/7.00% (\$\$)	365.59	196.00	169.59	46.39
Nett Amount (\$\$)	5,588.31	2,996.00	2,592.31	46.39

INSPECTION

Date of Assignment:	20/07/2022	
Date Inspected:	25/07/2022	Inspected At: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2022)
Parts:	144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD9787P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented/Bent	668.00 FL	*668.00 FL
2	1		*REAR BOOT CENTER LOGO	Not Necessary	85.00 FL	*- FL
3	1		*REAR BOOT CIVIC PLATE	Necessary	45.00 FL	*45.00 FL
4	1		*REAR BOOT TYPE R PLATE	Necessary	70.00 FL	*70.00 FL
5	1		*REAR BOOT LOCK	Serviceable	185.00 FL	*- FL
6	1		*REAR BOOT LAMP RH	Cracked	295.00 FL	*295.00 FL
7	1		*REAR RH TAIL LAMP	Not Necessary	381.00 FL	*- FL
8	1		*REAR BUMPER	Dented/Deformed	928.00 FL	*928.00 FL
9	1		*REAR BUMPER RETAINER RH	Bent	28.00 FL	*28.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
11	1		*REAR BUMPER REINFORCEMENT (NPA)	No such part	0.00 FL	*- FL
12	1		*REAR BUMPER LOWER SPOILER	Warped	285.00 FL	*285.00 FL
13	1		*REAR BUMPER LOWER SPOILER COVER	Not fitted	198.00 FL	*- FL
14	1		*REAR END PANEL	Repair	305.00 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	78.00 FL	*- FL
16	6		*TOP GARNISH CLIP	Not Necessary	47.40 FL	*- FL
17	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
					Sub Total (S\$)	3,903.40 2,574.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	730.68 474.80
					Total Parts (S\$)	3,172.72 2,099.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REPAIR REAR EXHAUST	New	150.00	0.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
4	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	120.00	50.00
5	LABOUR CHARGE	New	800.00	600.00
6	SPRAY PAINTING	New	800.00	700.00
Gross Labour Cost (\$)			2,050.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >