

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/07/22006875/4943

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 17k.

Code until 10-04-2028 LTA \$23348

30/7/22 L/S \$2800 informed AH yoy (Red to 2472, 462)

01/08/2023 5.50pm revised to Lynn Khong via Messenger.

Date/Time, File Pass to?

1) 07/08/2023

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.A. (\$

MEK-TP

2800

TOTAL

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247478
ATTN: Motor Claim Department

ESTIMATE

No : 22071901
Date : 19/07/2022
Policy No : GA458230
Veh Reg No : SJD9787P
Make / Model : HONDA CIVIC
Your Ref No : 22/CN/TP-143(07)
Claim Type : THIRT PARTY
Accident Date : 18/07/2022
TP Veh Reg No : SMS211D

Discription	Quantity	Unit Price	Amount
LIST PRICE:			
1 REAR BOOT <i>20/22</i>	1 PC		\$668.00
2 REAR BOOT CENTER LOGO <i>11</i>	1 PC		\$85.00
3 REAR BOOT "CIVIC" PLATE <i>ner</i>	1 PC		\$45.00
4 REAR BOOT "TYPE R" PLATE <i>ner</i>	1 PC		\$70.00
5 REAR BOOT LOCK <i>22</i>	1 PC		\$185.00
6 REAR BOOT LAMP RH <i>22</i>	1 PC		\$295.00
7 REAR RH TAIL LAMP <i>11</i>	1 PC		\$381.00
8 REAR BUMPER <i>20/22</i>	1 PC		\$928.00
9 REAR BUMPER RETAINER RH <i>22</i>	1 PC		\$28.00
10 REAR BUMPER CLIPS <i>ner</i>	10 PCS	\$5.50	\$55.00
11 REAR BUMPER REINFORCEMENT <i>NS</i>	1 PC		\$285.00
12 REAR BUMPER LOWER SPOILER <i>intermed</i>	1 PC		\$198.00
13 REAR BUMPER LOWER SPOILER COVER <i>NS</i>	1 PC		\$305.00
14 REAR END PANEL <i>2</i>	1 PC		\$78.00
15 REAR END PANEL TOP GARNISH <i>11</i>	1 PC		\$47.40
16 TOP GARNISH CLIP <i>11</i>	6 PCS	\$7.90	
TOTAL			\$3,653.40
-20.00%			\$730.68
			\$2,922.72

18f SPECIAL NET		
REVERSE SENSOR <i>shock</i>	200	\$250.00
TOTAL		\$250.00

Labour		
1 WIRE CHECKING	20	\$30.00
2 REPAIR REAR EXHAUST	11	\$150.00
3 REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	60	\$150.00
4 CAVITY PROTECTION ON ALL AFFECTED AREAS	50	\$120.00
5 LABOUR CHARGE	600	\$800.00
6 SPRAY PAINTING	700	\$800.00

TOTAL \$2,050.00

LKK Auto Consultants hence notify
the Receiver of the following
• Amount Before Excess \$5,222.72
• To resurvey before excess \$5,222.72
• To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Add GST @7% \$365.59
Total Amount Payable \$5,588.31

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

Not Authorized
22 March
25/7/22
4/5 @ 2800
4 days
2 hrs phd. After repair

3592