

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 3830R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,785.00	1,785.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	90.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH	CRACKED	80.00	80.00
2	FRONT BUMPER PARKING SENSOR	DAMAGED (1 PIECE ONLY)	820.00	260.00
7	FRONT BUMPER PARKING SENSOR 'O' RING	NECESSARY	70.00	70.00
7	FRONT BUMPER PARKING SENSOR HOLDER	NOT NECESSARY	525.00	-
2	FRONT BUMPER SIDE RETAINER L/R	NOT NECESSARY	110.00	-
1	FRONT BUMPER SPONGE	CRACKED	100.00	-
2	FRONT GRILLE L/R	N/S CRACKED	410.00	205.00
1	FRONT LH HEADLAMP	NOT NECESSARY	5,690.00	-
	LESS 5% DISCOUNT		-484.00	-120.00
			9,196.00	2,280.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	DENTED	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
			135.00	85.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSSING. (TO FR).		80.00	50.00
	TO RESET SYSTEM AFTER REPAIR WORKS.		400.00	100.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		500.00	250.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		500.00	250.00
			1,480.00	650.00
	GRAND TOTAL		10,811.00	3,015.00

Report Ref No. CS/SMR22006895/Avy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22006895/Avy3m4



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.