

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

STELLA LEE TZE MIEN
2
SINGAPORE 123456

Contact : 96555990, 94509091

TP SMRT.

VERON.

TAX INVOICE

Repair Code : CLM15593

Date in : 14/07/2022

Vehicle Num. : SMF3830R

Model : B.M.W. 730LI AT D/AB 4DR SR LED DSC NAV HUD

Chassis/Eng# : WBAYE22070DZ21215/11278889N52B30AF

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Delv</i>	1	1785.00	✓ 1,785.00
FRONT BUMPER LOWER GRILLE <i>new</i>	1	90.00	✓ 90.00 X
FRONT BUMPER NUMBER PLATE GARNISH <i>new</i>	1	80.00	✓ 80.00
FRONT BUMPER PARKING SENSOR <i>1 piece damaged</i>	2	410.00	260 820.00
FRONT BUMPER PARKING SENSOR 'O' RING <i>new</i>	7	10.00	✓ 70.00
FRONT BUMPER PARKING SENSOR HOLDER <i>new</i>	7	75.00	X 525.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	55.00	X 110.00
FRONT BUMPER SPONGE <i>new</i>	1	100.00	X 100.00
FRONT GRILLE L/R <i>new</i>	2	205.00	205 410.00
FRONT LH HEADLAMP <i>new</i>	1	5690.00	X 5,690.00
Subtotal before discount			9,680.00
Percentage discount 5%			484.00
Sub-total 1			9,196.00
FRONT BUMPER CLIPS - SET <i>new</i>	1	60.00	30 60.00
FRONT BUMPER NUMBER PLATE <i>Delv</i>	1	25.00	✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>Delv</i>	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

STELLA LEE TZE MIEN
2
SINGAPORE 123456

Contact : 96555990, 94509091

TAX INVOICE

Repair Code : CLM15593
Date in : 14/07/2022
Vehicle Num. : SMF3830R
Model : B.M.W. 730LI AT D/AB 4DR SR LED DSC NAV HUD
Chassis/Eng# : WBAYE22070DZ21215/11278889N52B30AF

Subtotal before discount	85	135.00
Percentage discount 0%		0.00
Sub-total 2		135.00
Parts-total		9,331.00

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works


To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	1,480.00
Parts & Labour Total	10,811.00

*** This is a computer-generated document which requires no signature.***

page 2



Adrian L
4/5 03/08/22
03 days
Total: 2876
4/5 2.31c ✓