

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 18.07.2022

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNB4905L**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 18.07.2022
TIME OF ACCIDENT : 14:40HRS

AGH309028192

2021 August.

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,867.40	\$ 1,867.40
2	FRONT DOOR LOWER GUARD RH <i>Dented</i>	1	\$ 1,098.70	\$ 1,098.70
3	FRONT DOOR INNER TRIM RH <i>new</i>	1	\$ 2,118.80	\$ 2,118.80
4	FRONT DOOR OUTER STRIP RH <i>2</i>	1	\$ 177.60	\$ 177.60
5	FRONT DOOR WEATHER STRIP RH	1	\$ 279.30	\$ 279.30
6	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 581.70	\$ 581.70
7	FRONT DOOR LOCK CATCH RH	1	\$ 35.10	\$ 35.10
8	FRONT DOOR STOPPER RH	2	\$ 19.80	\$ 39.60
9	FRONT DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 647.20	\$ 647.20
10	FRONT DOOR REGULATOR RH <i>new</i>	1	\$ 387.60	\$ 387.60
11	SLIDING DOOR LOWER GUARD RH <i>Dented</i>	1	\$ 867.60	\$ 867.60
12	SLIDING DOOR LOWER WEATHERSTRIP RH <i>new</i>	1	\$ 85.70	\$ 85.70

3347.40

2510.55

TOTAL PRICE \$ 8,186.30
LESS 25% \$ 2,046.58
SUB TOTAL PRICE \$ 6,139.73

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
2	FRONT DOOR LOWER GUARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT DOOR INNER TRIM BOARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	SLIDING DOOR LOWER GUARD CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 310.00

100

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNB4905L**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 18.07.2022
 TIME OF ACCIDENT : 14:40HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	450
3	TURFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 250.00	30
5	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	x
6	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	40
7	REMOVE AND REFIX FRONT WINDOW GLASS LH	\$ 60.00	40
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x

890

TOTAL \$3,160.00

Adrian Lij
 4/s 20/07/22.
 03 days.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,449.73
 TOTAL LABOUR COST : \$ 3,160.00
 TOTAL REPAIR COST : \$ 9,609.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3500.55

4/s: 2.8K

2.8K