

HUA MENG SPRAY PAINTING WORKSHOP

Repairer of the following:

• resurvey before/after spray painting
• to display damaged part(s) during resurvey

Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP SmRT.

Veron

ESTIMATE

Name : NG GEOK LENG

Vehicle No : SJF 5448 J

Make/Model : TOYOTA VIOS

Accident date : 16.07.2022

MR053HY9305065460

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front LH door side mirror <i>Dented</i>	1	\$ 2,170.10 890.
2	Front LH door side mirror housing <i>Missing</i>	1	\$ 200.10 89.
3	Front LH door side mirror signal lamp <i>Dented</i>	1	\$ 1,339.20 1215.
4	Front LH door <i>Dented</i>	1	\$ 200.30 X
5	Front LH door glass outer moulding <i>Not nec</i>	1	\$ 189.50 ✓
6	Front LH door protector <i>ht</i>	1	\$ 190.00 X
7	Front LH door top hinge	1	\$ 190.00 X
8	Front LH door lower hinge	1	\$ 200.50 X
9	Front LH door stopper	1	\$ 617.80 X
10	Front LH door inner lock	1	\$ 804.40 X
11	Front LH door inner board	1	\$ 187.10 X
12	Front LH door outer handle	1	\$ 639.20 X
13	Front LH door power window motor <i>Not nec</i>	1	\$ 254.50 X
14	Front LH door power window regulator	1	\$ 694.50 X
15	LH door centre pillar <i>Not nec</i>	1	\$ 1,079.60 ✓
16	Rear LH door <i>Dented</i>	1	\$ 190.00 X
17	Rear LH door outer glass moulding <i>Not nec</i>	1	\$ 188.60 ✓
18	Rear LH door protector <i>ht</i>	1	\$ 188.60 X
19	Rear LH door top hinge <i>Not nec</i>	1	\$ 188.60 X
20	Rear LH door lower hinge	1	\$ 200.50 X
21	Rear LH door stopper	1	\$ 860.10 X
22	Rear LH door inner board	1	\$ 210.60 X
23	Rear LH door power window regulator <i>Not nec</i>	1	\$ 617.80 X
24	Rear LH door power window motor	1	\$ 11,601.60
			\$ 2,900.40
Less 25% Disc			\$ 8,701.20
Total			

Special Nett Items

1	Front LH door frame black sticker (1 set) <i>Not nec</i>	1	\$ 188.60 80
2	Rear LH door frame black sticker (1 set)	1	\$ 133.20 80
Total			\$ 321.80

Labour Cost

1	Remove & reinstall door glass <i>Not nec</i>	\$ 200.00 160.
2	Remove, replace & repair consistent to the accident	\$ 1,400.00 500
3	Respray painting	\$ 1,200.00 500
4	Tuff kote	\$ 100.00 50
Total		\$ 2,900.00
Grand Total		\$ 11,923.00

3.3K

05 days

Total: 4108.77
h/s 3.3K