

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Ţ.				
		Affiliated to Federation Internation	nale Des Experts Er	n Automo	obile CS3/	CTI22003326
	CHINA TAIPING IN	NSURANCE (S) PTE LTD		Ref:	-000/OT1220	••
	3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date:	-11/04/2022	18/07/2022
	O O.			Code:	CTI	
١.		Policy Particulars :	- (THIRD PART)	/ CLAII	VI)	
	Insured Veh.	GBJ 3082S	Veh. Inspected	ł	SKN 1866H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM22D202454/C02/GBJ3082 S/LEWLC	Excess (\$)		0.00	
	Assign From	JENNY LEW	Assign Date		11/04/2022	18/07/2022
2.		Vehicle Partic	culars & Conditi	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.		Conditi	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
١.	T	Description	on of Damages			
5.		General	I Information			
<i>-</i> -	Accident Date	09/04/2022	Inspection Dat	·e	12/04/2022	
	Survey held at	7 SIN MING INDUSTRIAL ESTA	<u> </u>		, 0 ., _ 0	
	Repairer	GUAN AUTO SERVICE				
ia.	Tropull of	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					