



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2207686

INV Date 14/12/2022

Reference CC4/LPC22006910/Epa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SGE 6598T

Insured Veh. GBB 6395L

Claim No. 22/22/22/VC05/026020

Policy No.

Accident Date 05/07/2022

Inspection Date 22/07/2022

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 250.00        |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>250.00</b> |
| <b>GST (7%)</b>     | <b>17.50</b>  |
| <b>Grand Total</b>  | <b>267.50</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                  |   |  |   |            |
|--|---|--|---|------------|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE SINGAPORE 199555 |   |  | Ref: CC4/LPC22006910/Epa3q2<br>Date: 14/12/2022<br>Code: LPC2 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                  |   |  |   |            |
|  | Insured Veh.  | GBB 6395L  | Veh. Inspected  | SGE 6598T  |
|  | Policy No.  |  | Coverage (\$)   | 0.00       |
|  | Claim No.   | 22/22/22/VC05/026020   | Excess (\$)   | 0.00       |
|  | Assign From   | ENG HUEY NI  | Assign Date   | 12/07/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                      |   |  |   |            |
|  | Make & Model  | TOYOTA COROLLA   | c.c   | 1598       |
|  | Engine No.  | HIDDEN   | Year of Reg.  | 2006       |
|  | Chassis No.   | MR053ZEC107113954  | Colour  | SILVER     |
|  | Odometer  | 229943 KM  | Steering  | IN ORDER   |
|  | Brakes  | IN ORDER   | Modification  | SPORTS RIM |
|  | General   | FAIR   |   |            |
| <b>3. Conditions of Tyres</b>  |   |  |   |            |
|  |   | Size   | Make  | Balance    |
|  | R/H Front Tyre  | 185/55 R15   | GOODYEAR  | 4 mm       |
|  | L/H Front Tyre  | 185/55 R15   | GOODYEAR  | 4 mm       |
|  | R/H Rear Tyre   | 185/55 R15   | GOODYEAR  | 4 mm       |
|  | L/H Rear Tyre   | 185/55 R15   | GOODYEAR  | 4 mm       |
| <b>4. Description of Damages</b>   |   |  |   |            |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br><br>DAMAGES SEE DETAILS.   |  |   |            |
| <b>5. General Information</b>  |   |  |   |            |
|  | Accident Date   | 05/07/2022   | Inspection Date   | 22/07/2022 |
|  | Survey held at  | GOLDBELL ENGINEERING PTE LTD<br>10 TUAS AVE 18<br>SINGAPORE 638894 |   |            |
| <b>5a. Remarks</b>   |   |  |   |            |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |   |            |
| <b>5b. Estimate Days of Repair</b>   |   |  |   |            |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:   |  | 3 Working Days  |            |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### OPINION ON REPAIR COST FOR VEHICLE NO. SGE 6598T

| Qty                                | Description of Parts  | Condition | Recommended (\$) |
|------------------------------------|---|-----------|------------------|
| 1                                  | <b><u>REPLACEMENT OF PARTS</u></b>  | CRUSHED   |                  |
|                                    | FRONT BUMPER  |           | 229.50           |
|                                    |   |           | 229.50           |
|                                    | <b><u>LABOUR</u></b>  |           |                  |
|                                    | TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ,ETC.   |           | 200.00           |
|                                    | TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL<br>BEAT ,STRAIGHTEN & REALIGN ,ETC. |           | 200.00           |
|                                    |   |           | 400.00           |
| <b>GRAND TOTAL</b>                 |   |           | <b>629.50</b>    |
| <b>RECOMMENDED COST OF REPAIRS</b> |   |           | <b>629.50</b>    |

Report Ref No. CC4/LPC22006910/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SGE 6598T

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

