

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22006911/AEA3Q2**Date:** 11/04/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKJ1400P**Insured Vehicle No :** SBP3688M

Date of Loss: 15/07/2022

Nature of Claim: TP

Claim No: 5222328111SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKJ1400P**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK074103

Reg. Date: 28/03/2019 (Man. Year: 2018) Chassis No: WAUZZZF53KA014473

Colour: White Odometer: 95351 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,124.00	10,875.76	15,248.24	58.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,672.00	3,022.00	6,650.00	68.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,796.00	13,897.76	21,898.24	61.18
+ GST 8.00/8.00% (S\$)	2,863.68	1,111.82	1,751.86	61.18
Nett Amount (S\$)	38,659.68	15,009.58	23,650.10	61.18
+ Car Rental (6.0 x S\$150.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,911.58		

INSPECTION

Date of Assignment: 20/07/2022

Date Inspected: 20/07/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
5	1		*FRONT AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	529.00 FS	*423.20 FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	41.00 FS	*32.24 FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
9	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
13	1		*FRONT PARKING AID SENSOR	Not Necessary	265.00 FS	*- FS
14	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*FRONT FENDER - RH	Dented	1,189.00 FS	*951.20 FS
16	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
17	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	83.00 FS	*65.84 FS
18	1		*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
19	6		*FRONT FENDER POP RIVET	Not Necessary	23.00 FS	*- FS
20	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
21	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
22	1		*FRONT FENDER WHEEL HOUSING LINER - RH	Deformed	299.00 FS	*238.80 FS
23	1		*FRONT WHEEL SPOILER - LH	Deformed	82.00 FS	*65.12 FS
24	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	40.00 FS	*- FS
25	1		*FRONT FENDER CHROME	Necessary	171.00 FS	*136.40 FS
26	1		*FRONT FENDER COVER	Damaged	40.00 FS	*31.44 FS
27	1		*FRONT FENDER HEADLIGHT PROTECTOR COVER - RH	Not Necessary	18.00 FS	*- FS
28	1		*FRONT LED HEADLIGHT - RH	Cut	8,416.00 FS	*6,732.80 FS
29	1		*FRONT LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
30	1		*FRONT LIFT CYLINDER BRACKET - RH	Not Necessary	17.00 FS	*- FS
31	1		*FRONT LIFT CYLINDER HOSE - RH	Not Necessary	100.00 FS	*- FS
32	1		*FRONT DOOR CHROME TRIM - RH	Not Necessary	171.00 FS	*- FS
33	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	1,889.00 FS	*- FS
34	1		*FRONT ALUMINIUM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
35	1		*FRONT WISHBONE LINK - RH	Not Necessary	605.00 FS	*- FS
36	1		*FRONT SUSPENSION GUIDE - RH	Not Necessary	1,057.00 FS	*- FS
37	2		*FRONT AND REAR CONTROL ARM GUIDE - RH UPPER	Not Necessary	1,150.00 FS	*- FS
38	1		*FRONT WHEEL BEARING HOUSING - RH	Not Necessary	1,070.00 FS	*- FS
39	1		*FRONT SWIVEL JOINT - RH	Not Necessary	214.00 FS	*- FS
40	1		*FRONT WHEEL HUB - RH	Not Necessary	498.00 FS	*- FS
41	1		*FRONT FLANGE DOUBLE ANGLED BALL BEARING	Not Necessary	273.00 FS	*- FS
42	1		*FRONT WHEELHUB WITH BEARING	Not Necessary	884.00 FS	*- FS
43	1		*FRONT SUSPENSION FORKS - RH	Not Necessary	293.00 FS	*- FS
44	2		*FRONT COUPLING ROD	Not Necessary	258.00 FS	*- FS
45	1		*FRONT GAS SHOCK ABSORBER	Not Necessary	323.00 FS	*- FS
46	1		*FRONT TRACK ROD	Not Necessary	109.00 FS	*- FS
47	1		*FRONT TIE ROD END - RH	Not Necessary	217.00 FS	*- FS
48	1		*SUNDRIES	Necessary	700.00 FS	*21.12 FS
49	1		*RHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
50	1		*STONE CHIP GUARD - RH	Damaged	57.00 FS	*45.28 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 26,124.00 10,875.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR	New	280.00	0.00
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY	New	2,400.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR	New	3,000.00	1,100.00
7	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,672.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >