

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0600/2022/EQ  
**DATE** : 19-Jul-22  
**WIP** : 33246

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/7/2022.**

**AXA Insurance Pte Ltd**

No 8 Shenton Way

#27-01 AXA Tower

Singapore 068811

ALG

**OWNER'S NAME** : MR LIM CHIEN JOO DERICK  
**ADDRESS** : 25 ELIAS ROAD  
#10-10  
SINGAPORE 519931  
**TELEPHONE** : HP +65 93873238  
**TYPE OF CLAIM** : ~~OWN-DAMAGE CLAIM~~ *Third Party Claim*  
**POLICY NO** : GA614326  
**VEHICLE NO** : **SKJ 1400 P**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 28/3/2019  
**ENGINE NO** : CVK 074103  
**CHASSIS NO** : WAUZZZF53KA014473  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 15-Jul-22  
**PLACE OF ACCIDENT** : 507 TAMPINES CENTRAL 1 MULTI STOREY CARPARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 1400 P**

| S/N                             | NATURE OF JOBS                                                                                                                                   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                               | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ 480.00        | ✓ ✓                        |
| 2                               | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                            | S/N \$ 400.00        | 250 ✓                      |
| 3                               | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.        | S/N \$ 280.00        | +                          |
| 4                               | TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.                                                                                             | S/N \$ 2,400.00      | +                          |
| 5                               | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.   | \$ 2,400.00          | 1000 ✓                     |
| 6                               | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.                                                                                    | \$ 3,000.00          | 1100 ✓                     |
| <b>SUB-TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | <b>: \$ 8,960.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 1400 P**

| S/N                         | NATURE OF JOBS                                                           | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------|----------------------|-------------------------------|
| 7                           | TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. | S/N \$ 520.00        | +                             |
| 8                           | TO CARRY OUT DIAGNOSTIC CHECK.                                           | S/N \$ 192.00        | ✓                             |
| <b>TOTAL LABOUR CHARGES</b> |                                                                          | <b>: \$ 9,672.00</b> |                               |

Car-in

23/8/22

wip: 33246

Benoi

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adrian  
- 4 days

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SK11400 P

|                       |                                                         |     | DAMAGED PARTS & PRICES |         |          |
|-----------------------|---------------------------------------------------------|-----|------------------------|---------|----------|
| S/N                   | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS |          |
| 1                     | FRONT BUMPER <i>Rehomed</i>                             | 1   | \$ 2,493.00            | ✓       | 1,994.40 |
| 2                     | FRONT BUMPER FIXING PARTS <i>mean</i>                   | 1   | \$ 425.00              | +       |          |
| 3                     | FRONT BUMPER SECURING STRIP <i>mean</i>                 | 2   | \$ 79.00               | +       |          |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>mean</i> | 1   | \$ 254.00              | +       |          |
| 5                     | FRONT AIR GUIDE - RH <i>X NN</i>                        | 1   | \$ 72.00               | X       |          |
| 6                     | FRONT BUMPER AIR GUIDE GRILLE - RH <i>Curt.</i>         | 1   | \$ 529.00              | +       | 423.20   |
| 7                     | FRONT BUMPER GUIDE SECTION - RH <i>mean</i>             | 1   | \$ 41.00               | ✓       | 32.24    |
| 8                     | FRONT BUMPER TOP COVER <i>mean</i>                      | 1   | \$ 143.00              | +       |          |
| 9                     | CAUTION SIGN STICKER <i>mean</i>                        | 1   | \$ 16.00               | +       |          |
| 10                    | AIR CONDITIONER STICKER <i>mean</i>                     | 1   | \$ 9.00                | +       |          |
| 11                    | FRONT BUMPER FOAM FILLER PIECE <i>mean</i>              | 1   | \$ 139.00              | +       |          |
| 12                    | FRONT BUMPER REINFORCEMENT BEAM <i>mean</i>             | 1   | \$ 899.00              | +       |          |
| 13                    | FRONT PARKING AID SENSOR <i>mean</i>                    | 1   | \$ 265.00              | +       |          |
| 14                    | FRONT PARKING AID SENSOR SEAL RING <i>mean</i>          | 4   | \$ 10.00               | +       |          |
| 15                    | FRONT FENDER - RH <i>Dented</i>                         | 1   | \$ 1,189.00            | ✓       | 951.20   |
| 16                    | FRONT FENDER ATTACHMENT PARTS <i>mean</i>               | 1   | \$ 55.00               | +       |          |
| 17                    | FRONT FENDER CLOSING ELEMENT - RH <i>Best</i>           | 1   | \$ 65.84               | 83.00   | ✓        |
| 18                    | FRONT FENDER BRACKET - RH <i>Best</i>                   | 1   | \$ 32.72               | 41.00   | ✓        |
| 19                    | FRONT FENDER POP RIVET <i>X NN</i>                      | 6   | \$ 23.00               | X       |          |
| 20                    | FRONT FENDER BRACE - RH <i>Best</i>                     | 1   | \$ 132.00              | ✓       | 105.20   |
| SUB TOTAL SPARE PARTS |                                                         | :   | \$ 6,897.00            |         |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SK1 1400 P

|                       |                                               |     |              | DAMAGED PARTS & PRICES |          |
|-----------------------|-----------------------------------------------|-----|--------------|------------------------|----------|
| S/N                   | PARTS DESCRIPTION                             | QTY | S/NETT       | REMARKS                |          |
| 21                    | FRONT FENDER DEFORMATION ELEMENT BRACKET - RH | 1   | \$ 55.00     | X                      |          |
| 22                    | FRONT FENDER WHEEL HOUSING LINER - RH         | 1   | \$ 299.00    |                        | 238.80   |
| 23                    | FRONT WHEEL SPOILER - RH                      | 1   | \$ 65.12     | 82.00                  | ✓        |
| 24                    | FRONT WHEEL SPOILER TRIM - RH                 | 1   | \$ 40.00     |                        |          |
| 25                    | FRONT FENDER CHROME                           | 1   | \$ 136.40    | 171.00                 | ✓        |
| 26                    | FRONT FENDER COVER                            | 1   | \$ 31.44     | 40.00                  | ✓        |
| 27                    | FRONT FENDER HEADLIGHT PROTECTOR COVER - RH   | 1   | \$ 18.00     | X                      |          |
| 28                    | FRONT LED HEADLIGHT - RH                      | 1   | 8416         |                        | 6,732.80 |
| 29                    | FRONT LIFT CYLINDER - RH                      | 1   | \$ 217.00    |                        |          |
| 30                    | FRONT LIFT CYLINDER BRACKET - RH              | 1   | \$ 17.00     |                        |          |
| 31                    | FRONT LIFT CYLINDER HOSE - RH                 | 1   | \$ 100.00    |                        |          |
| 32                    | FRONT DOOR CHROME TRIM - RH                   | 1   | \$ 171.00    |                        |          |
| 33                    | FRONT ALUMINIUM RIM - RH                      | 1   | \$ 1,889.00  |                        |          |
| 34                    | FRONT ALUMINIUM RUBBER VALVE                  | 1   | \$ 4.00      |                        |          |
| 35                    | FRONT WISHBONE LINK - RH                      | 1   | \$ 605.00    |                        |          |
| 36                    | FRONT SUSPENSION GUIDE - RH                   | 1   | \$ 1,057.00  |                        |          |
| 37                    | FRONT AND REAR CONTROL ARM GUIDE - RH UPPER   | 2   | \$ 1,150.00  |                        |          |
| 38                    | FRONT WHEEL BEARING HOUSING - RH              | 1   | \$ 1,070.00  |                        |          |
| 39                    | FRONT SWIVEL JOINT - RH                       | 1   | \$ 214.00    |                        |          |
| 40                    | FRONT WHEEL HUB - RH                          | 1   | \$ 498.00    |                        |          |
| SUB TOTAL SPARE PARTS |                                               |     | \$ 16,113.00 |                        |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 1400 P**

|                             |                                         |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|-----------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                       | QTY | S/NETT                 | REMARKS |
| 41                          | FRONT FLANGE DOUBLE ANGLED BALL BEARING | 1   | \$ 273.00              | X       |
| 42                          | FRONT WHEELHUB WITH BEARING             | 1   | \$ 884.00              | X       |
| 43                          | FRONT SUSPENSION FORKS - RH             | 1   | \$ 293.00              | X       |
| 44                          | FRONT COUPLING ROD                      | 2   | \$ 258.00              | X       |
| 45                          | FRONT GAS SHOCK ABSORBER                | 1   | \$ 323.00              | X       |
| 46                          | FRONT TRACK ROD                         | 1   | \$ 109.00              | X       |
| 47                          | FRONT TIE ROD END - RH                  | 1   | \$ 217.00              | X       |
| 48                          | SUNDRIES                                |     | \$ 700.00              | ✓ 21.12 |
| 49                          | RHS FRONT TYRE                          |     | TBC                    | X       |
| <b>TOTAL SPARE PARTS</b>    |                                         | :   | <b>\$ 26,067.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                         | :   | <b>\$ 9,672.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                         | :   | <b>\$ 35,739.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian King

SURVEYED DATE

:

20/07/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**

**Date**

**Service Advisor**

**Pages**

**Regn No**

**Model No**

PA/TP/0600/2022/EQ

30-Aug-22

CHANG


1 of 1

SKJ 1400 P

AUDI A5 SPORTBACK 2.0 TFSI

| Quantity           | Description                            | Unit Price      | Amount  |
|--------------------|----------------------------------------|-----------------|---------|
| <u>Parts</u>       |                                        |                 |         |
| 1                  | STONE CHIP GUARD - RH <i>Replaced.</i> | \$ 57.00        | ✓ 45.28 |
| <b>GRAND TOTAL</b> |                                        | <b>\$ 57.00</b> |         |

For Premium Automobiles Pte Ltd



Authorised Signature

*Adrian Ling*  
*Replaced fls*