

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22006912/AYA3Q2**Date:** 13/04/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SMT760E **Insured Vehicle No :** SNC3148G

Date of Loss: 19/07/2022 Nature of Claim: TP Claim No: MFL2022D0003851

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT760E**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB6744964
 Reg. Date: 26/03/2020 (Man. Year: 2018) Chassis No: RU31324955
 Colour: Silver Odometer: 99877 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,435.76	1,034.00	6,401.76	86.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	950.00	2,790.00	74.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,175.76	1,984.00	9,191.76	82.25
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	11,175.76	1,500.00	9,675.76	86.58
+ GST 8.00/8.00% (S\$)	894.06	120.00	774.06	86.58
Nett Amount (S\$)	12,069.82	1,620.00	10,449.82	86.58
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		1,860.00		
Liabe Amount (50.00%) (S\$)		930.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		937.45		

INSPECTION

Date of Assignment: 20/07/2022

Date Inspected: 25/07/2022 Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM
 Inspection Centre
 Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2022)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMT760E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	855.20 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	62.40 FL	*- FL
3	1		*FRONT FENDER RH	Dented	620.50 FL	*545.00 FL
4	1		*FRONT FENDER INNER COWLING	Not Necessary	211.60 FL	*- FL
5	1		*FRONT FENDER WHEEL ARCH	Cut	320.20 FL	*185.00 FL
6	1		*FRONT LOWER ARM	Not Necessary	388.20 FL	*- FL
7	1		*FRONT KNUCKLE ARM	Not Necessary	311.50 FL	*- FL
8	1		*FRONT KNUCKLE ARM BEARING	Not Necessary	211.20 FL	*- FL
9	1		*FRONT SHOCK ABSORBER	Not Necessary	420.50 FL	*- FL
10	1		*FRONT DOOR	Not Necessary	1,588.20 FL	*- FL
11	1		*FRONT DOOR STICKER	Not Necessary	112.50 FL	*- FL
12	1		*REAR DOOR	Not Necessary	1,655.20 FL	*- FL
13	1		*REAR DOOR STICKER	Not Necessary	112.50 FL	*- FL
14	1		*SET FRONT BUMPER CLIPS	Not Necessary	20.00 FS	*- FS
15	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
16	1		*DOOR PROTECTOR STRIPE	Not Necessary	120.00 FS	*- FS
17	1		*SET WHEEL RIM	Cut	1,400.00 FS	*450.00 FS
18	1		*WHEEL TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,809.70	1,180.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,373.94	146.00
Total Parts (\$\$)	7,435.76	1,034.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	400.00
3	TUFF COAT	New	100.00	40.00
4	WIRING CHECK	New	250.00	30.00
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	250.00	0.00
6	FOUR WHEEL ALIGNMENT	New	100.00	80.00
7	TO REMOVE AND REFIX FRONT DOOR MECHANISM	New	120.00	0.00
8	TO REMOVE AND REFIX REAR DOOR MECHANISM	New	120.00	0.00
Gross Labour Cost (S\$)			3,740.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >