

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2207-378
DATE : 19-Jul-2022
POLICY NO. : P10491396R01
VEHICLE REG. NO. : SMG7512C
VEHICLE MAKE : HONDA CROSSROAD 2.0X ATO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Upper Retainer RH	1	\$ 40.00	\$ 40.00
4	Rear Bumper Upper Retainer LH	1	\$ 40.00	\$ 40.00
5	Rear Bumper Lower Retainer RH	1	\$ 38.00	\$ 38.00
6	Rear Bumper Lower Retainer LH	1	\$ 38.00	\$ 38.00
7	Rear Bumper Side Cover RH	1	\$ 250.00	\$ 250.00
8	Rear Bumper Side Cover LH	1	\$ 250.00	\$ 250.00
9	Rear Bumper Reflector RH	1	\$ 100.00	\$ 100.00
10	Rear Bumper Reflector LH	1	\$ 100.00	\$ 100.00
11	Rear Tow Eye Cover	1	\$ 80.00	\$ 80.00
12	Rear Emblem	1	\$ 60.00	\$ 60.00
13	Tailgate	1	\$ 1,300.00	\$ 1,300.00
14	Tailgate Outer Cover	1	\$ 750.00	\$ 750.00
15	Tailgate Lock Assy	1	\$ 170.00	\$ 170.00
16	Rear Windscreen Moulding Assy	1	\$ 150.00	\$ 150.00
17	End Panel Top Garnish	1	\$ 260.00	\$ 260.00
18	End Panel Assy	1	\$ 635.00	\$ 635.00
Total Spare Parts				\$ 5,561.00
	<u>SPECIAL NETT</u>			
19	Rear License Plate with Casing	1	\$ 40.00	\$ 40.00
20	Rear Bumper Lower Diffuser	1	\$ 380.00	\$ 380.00
21	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
22	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 660.00
	<u>LABOUR</u>			
23	Spray Paint (Rear Bumper, Rear Bumper Cover RH/LH, Tailgate, Tailgate Cover & Inner Panels)	1	\$ 1,000.00	\$ 1,000.00
24	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00
25	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 350.00	\$ 350.00
26	Repair, Re-Align & Panel Beat End Panel & Spare Tyre Sink	1	\$ 150.00	\$ 150.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-378
DATE : 19-Jul-2022
POLICY NO. : P10491396R01
VEHICLE REG. NO. : SMG7512C
VEHICLE MAKE : HONDA CROSSROAD 2.0X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
27	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
28	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
29	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
30	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,830.00
Amount Before Excess	\$ 9,051.00
Add GST @ 7%	633.57
Total Amount Payable	\$ 9,684.57