

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2207-378

DATE : 19-Jul-2022

POLICY NO. : P10491396R01

VEHICLE REG. NO. : SMG7512C

VEHICLE MAKE : HONDA CROSSROAD 2.0X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Kennerth Heng @ lkkauto.com

4-5 days

Not Authorised
11 Pym @ 2800/hr
Permy After Paim
Kennerth 96910663

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>1134</i>	<i>Avulcm</i> 1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips	<i>nn</i> 10	\$ 5.00	\$ 50.00
3	Rear Bumper Upper Retainer RH	<i>nn</i> 1	\$ 40.00	\$ 40.00
4	Rear Bumper Upper Retainer LH	<i>nn</i> 1	\$ 40.00	\$ 40.00
5	Rear Bumper Lower Retainer RH	<i>nn</i> 1	\$ 38.00	\$ 38.00
6	Rear Bumper Lower Retainer LH	<i>nn</i> 1	\$ 38.00	\$ 38.00
7	Rear Bumper Side Cover RH	<i>nn</i> 1	\$ 250.00	\$ 250.00
8	Rear Bumper Side Cover LH	<i>nn</i> 1	\$ 250.00	\$ 250.00
9	Rear Bumper Reflector RH	<i>nn</i> 1	\$ 100.00	\$ 100.00
10	Rear Bumper Reflector LH	<i>nn</i> 1	\$ 100.00	\$ 100.00
11	Rear Tow Eye Cover	<i>nn</i> 1	\$ 80.00	\$ 80.00
12	Rear Emblem	<i>nn</i> 1	\$ 60.00	\$ 60.00
13	Tailgate	<i>nn</i> 1	\$ 1,300.00	\$ 1,300.00
14	Tailgate Outer Cover <i>691</i>	<i>cm</i> 1	\$ 750.00	\$ 750.00
15	Tailgate Lock Assy	1	\$ <i>nn</i> 170.00	\$ 170.00
16	Rear Windscreen Moulding Assy	<i>nn</i> 1	\$ 150.00	\$ 150.00
17	End Panel Top Garnish	<i>nn</i> 1	\$ 260.00	\$ 260.00
18	End Panel Assy	<i>208</i> <i>nn</i> 1	\$ 635.00	\$ 635.00
Total Spare Parts				\$ 5,561.00
SPECIAL NETT				
19	Rear License Plate with Casing	<i>cm</i> 1	\$ 40.00	\$ 40.00
20	Rear Bumper Lower Diffuser	<i>nn</i> 1	\$ 380.00	\$ 380.00
21	Rear Windscreen Sealant	1	\$ <i>nn</i> 40.00	\$ 40.00
22	Reverse Sensor	<i>nn</i> 1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 660.00
LABOUR				
23	Spray Paint (Rear Bumper, Rear Bumper Cover RH/LH, Tailgate, Tailgate Cover & Inner Panels)	1	\$ 1,000.00	\$ 1,000.00
24	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00
25	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 350.00	\$ <i>nn</i> 350.00
26	Repair, Re-Align & Panel Beat End Panel & Spare Tyre Sink	1	\$ 150.00	\$ <i>nn</i> 150.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-378

DATE : 19-Jul-2022

POLICY NO. : P10491396R01

VEHICLE REG. NO. : SMG7512C

VEHICLE MAKE : HONDA CROSSROAD 2.0X A

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
27	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
28	Remove and Refit Rear Windscreen	1	\$ 120.00 120.00	\$ 120.00
29	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00 100.00	\$ 100.00
30	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,830.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Amount Before Excess	\$ 9,051.00
Add GST @ 7%	633.57
Total Amount Payable	\$ 9,684.57

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: