

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0594/2022/EQ
DATE : 18-Jul-22
WIP : 33172

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/07/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian
7 days exclude 1 Sunday
Johnny Boo 1 Nov 22

OWNER'S NAME : MDM GOH AH KENG, THERESA HUANG
ADDRESS : 150 LORONG J TELOK KURAU
#03-04
SINGAPORE 423491
TELEPHONE : HP +65 9635 2246
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210065544
VEHICLE NO : **SKQ 6060 S**
MODEL CODE : AUDI A4 2.0 TFSI
MODEL YEAR : 29/6/2021
ENGINE NO : DEM 028155
CHASSIS NO : WAUZZZF44MA021815
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Jul-22
PLACE OF ACCIDENT : BUS STOP JUST AFTER LORONG JUNCTION
BEFORE READING CHANGI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 6060 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	350.00	
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 560.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	\$ 2,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, BONNET, LHS WING MIRROR COVER, DOOR HANDLES AND LHS REAR DOOR.	\$	5,000.00	\$ 3,000.00
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,722.00	\$ 6,232.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 6060 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT AIR GUIDE - LH	1	\$ 51.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	
7	FRONT BUMPER TRIM - LH	1	\$ 54.00	
8	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	
9	FRONT FENDER - LH	1	\$ 1,227.00	\$ 981.60
10	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00	
11	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 81.00	
12	FRONT FENDER BRACKET - LH	1	\$ 41.00	
13	FRONT FENDER DEFORMARION ELEMENT BRACKET - LH	1	\$ 55.00	
14	FRONT POP RIVET	7	\$ 27.00	\$ 21.28
15	FRONT FENDER BRACE - LH	1	\$ 132.00	
16	FRONT FENDER WHEEL HOUSING LINER - LH	1	\$ 256.00	
17	FRONT WHEEL SPOILER - LH	1	\$ 82.00	
18	FRONT FENDER PROTECTION COVER - LH	1	\$ 35.00	
19	FRONT HEADLAMPS COVER - LH	1	\$ 49.00	
20	FRONT LED HEADLIGHT - LH	1	\$ 8,172.00	
SUB TOTAL SPARE PARTS		:	\$ 13,807.00	\$ 1,002.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 6060 S

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	1,002.88
21	FRONT LIFT CYLINDER - LH	1	\$	231.00	
22	FRONT LIFT CYLINDER BRACKET	1	\$	7.00	
23	FRONT CORRUGATED PIPE	1	\$	107.00	
24	FRONT DOOR - LH	1	\$	3,431.00	\$ 2,744.80
25	FRONT OUTER DOOR SEAL - LH	1	\$	229.00	\$ 182.80
26	BONDING AGENT	1	\$	51.00	
27	CLEANING SOLUTION	1	\$	74.00	
28	APPLICATOR	1	\$	8.00	
29	FRONT DOOR ATTACHMENT PARTS	1	\$	1,153.00	
30	FRONT DOOR CATCH - LH	1	\$	116.00	
31	FRONT OVAL HEXAGON SOCKET HEAD BOLT	2	\$	3.00	
32	FRONT EXTERIOR MIRROR MOUNTING - LH	1	\$	1,201.00	\$ 960.80
33	FRONT MIRROR CAP - LH	1	\$	308.00	
34	FRONT BEAM PLATE MIRROR GLASS - LH	1	\$	1,298.00	
35	FRONT DOOR HANDLE TRIM PLATE - RH	1	\$	98.00	
36	FRONT PASSENGER DOOR HOUSING	1	\$	9.00	
37	REAR DOOR - LH	1	\$	3,431.00	\$ 2,744.80
38	REAR OUTER DOOR SEAL - LH	1	\$	229.00	\$ 182.80
39	BONDING AGENT	1	\$	51.00	
40	CLEANING SOLUTION	1	\$	74.00	
SUB TOTAL SPARE PARTS		:	\$	12,109.00	\$ 7,818.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 6060 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	7,818.88
41	APPLICATOR	1	\$	8.00	
42	FRONT SEALING STRIP	1	\$	19.00	
43	REAR DOOR ATTACHMENT PARTS	1	\$	943.00	
44	REAR DOOR CATCH - LH	1	\$	134.00	
45	REAR OVAL HEXAGON SOCKET HEAD BOLT	2	\$	3.00	
46	SUNDRIES		\$	450.00	\$ 7.20
TOTAL SPARE PARTS		:	\$	27,473.00	\$ 7,826.08
TOTAL LABOUR CHARGES		:	\$	10,722.00	\$ 6,232.00
GRAND TOTAL		:	\$	38,195.00	\$ 14,058.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/10/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT