

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0472/2022/JT
DATE : 8-Jun-22
WIP : 27726

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 19/07/2022

YOUR INSURED VEH NO : GBD 8382 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
4 days - ok - Johnny Boo
27-Sep-22

OWNER'S NAME : MR JEFFREY NG LENG PING
ADDRESS : 193 LORONG 4 TOA PAYOH
#11-658
SINGAPORE 310193
TELEPHONE : HP +65 8223 2020
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210081614
VEHICLE NO : **SLB 2328 P**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S-TRONIC
MODEL YEAR : 29/7/2021
ENGINE NO : DKY 015446
CHASSIS NO : WAUZZZF24MN070259
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jun-22
PLACE OF ACCIDENT : LORONG 4 TOA PAYOH CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 2328 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	\$	2,500.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,972.00	\$ 3,022.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 2328 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,012.00	\$	2,409.60
2	FRONT BUMPER FIXING PARTS	1	\$ 658.00		
3	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 248.00		
4	FRONT BUMPER ADAPTER - RH	1	\$ 44.00		
5	FRONT BUMPER REINFORCEMENT - RH	1	\$ 125.00		
6	FRONT BUMPER GRILLE - LOWER CENTER	1	\$ 171.00		
7	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 235.00		
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 485.00		
9	FRONT BUMPER AIR GUIDE INNER - RH	1	\$ 33.00		
10	FRONT BUMPER AIR GUIDE OUTER - RH	1	\$ 24.00		
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 252.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,076.00		
13	FRONT BUMPER POP RIVET	6	\$ 6.00	\$	4.32
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 67.00		
15	FORNT BUMPER GUIDE SECTION - RH	1	\$ 50.00		
16	FORNT BUMPER BRACKET - RH	1	\$ 61.00		
17	FRONT BUMPER TOP COVER	1	\$ 140.00		
18	CAUTION STICKER	1	\$ 16.00		
19	FRONT PARKING AID SENSOR	1	TBC		
20	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
SUB TOTAL SPARE PARTS		:	\$ 6,713.00	\$	2,413.92

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 2328 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	2,413.92
21	FRONT FENDER - RH	1	\$ 1,649.00	\$	1,319.20
22	FRONT FENDER ATTACHMENT PARTS	1	\$ 44.00		
23	FRONT FENDER BRACE - RH	1	\$ 137.00	\$	109.60
24	FRONT FENDER BRACKET UPPER - RH	1	\$ 49.00		
25	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00		
26	FRONT WHEEL SPOILER - RH	1	\$ 185.00		
27	FRONT WHEEL SPOILER STONE CHIP GUARD - RH	1	\$ 57.00		
28	FRONT WHEEL SPOILER TRIM BRACKET - RH	1	\$ 45.00		
29	HEADLIGHT MOUNTING - RH	1	\$ 132.00		
30	HEADLIGHT MATRIX BEAM - RH	1	\$ 9,172.00	\$	7,337.60
31	LIFT CYLINDER - RH	1	\$ 217.00		
32	LIFT CYLINDER BRACKET - RH	1	\$ 7.00		
33	LIFT CYLINDER HOSE	1	\$ 204.00		
34	RADIATOR AIR GUIDE - RH	1	\$ 44.00		
35	SUNDRIES		\$ 350.00		
TOTAL SPARE PARTS			\$ 19,304.00	\$	11,180.32
TOTAL LABOUR CHARGES			\$ 5,972.00	\$	3,022.00
GRAND TOTAL			\$ 25,276.00	\$	14,202.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-7/09/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT