


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 4532 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✗	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR BOTH REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED ✓	\$ 3,000.00	8/8. 500 + 250 750
4	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS AND REAR END PANELLING. ✓	\$ 4,500.00	1650 + 550 2200 8/8
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>8,332.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>Deland</i>	1	\$ 3,188.00	✓ 2550.40
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 480.00	✓
3	REAR BUMPER SECURING STRIP <i>new</i>	1	\$ 249.00	✓ 198.80
4	REAR BUMPER SPOILER - LH / RH <i>new</i>	1	\$ 276.00	✓ 220.80
5	REAR BUMPER TRIM <i>Deland</i>	1	\$ 326.00	✓ 260.80
6	REAR BUMPER BRACKET (LH/RH) <i>Damaged</i>	2	\$ 260.00	✓ 208.00
7	REAR LIGHT REFLECTOR - LH / RH <i>LH cracked</i>	2	\$ 92.00	46.36.48
8	REAR LED LICENCE PLATE LIGHT <i>new</i>	2	\$ 209.00	+
9	REAR LED TAIL LIGHT - LH (RH) <i>- outer.</i>	2	\$ 2,270.00	+
10	REAR TRIM TAIL LIGHT - LH / RH <i>new</i>	2	\$ 68.00	+
11	REAR LED TAIL LIGHT - LH / RH	2	\$ 2,270.00	+
12	REAR TRIM TAIL LIGHT - LH / RH	2	\$ 68.00	+
13	REAR BUMPER BEAM <i>new</i>	1	\$ 1,131.00	+
14	REAR BUMPER SEAL	2	\$ 32.00	+
15	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 49.00	+
16	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 51.00	+
17	REAR BUMPER GUIDE SECTION (LH/RH) <i>Damaged</i>	2	\$ 52.00	✓ 40.30
18	REAR PIN <i>new</i>	2	\$ 6.00	+
19	REAR BUMPER HOLDING STRAP (LH/RH) <i>cracked</i>	2	\$ 188.00	✓ 149.60
20	REAR RETAINER FOR AERIAL - LH <i>new</i>	1	\$ 29.00	+
SUB TOTAL SPARE PARTS		:	\$ 11,294.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR TELEPHONE AERIAL	2	\$ 384.00	+	
22	REAR OPENING BOOT LID CONTROL UNIT	1	\$ 454.00	+	
23	REAR TAILGATE OPENING SENSOR LINE	1	\$ 228.00	+	
24	REAR BUMPER CONTROL UNIT RETAINER	1	\$ 9.00	+	
25	REAR BUMPER CROSS PANEL	1	\$ 120.00	+	
26	REAR SENSOR - INNER / OUTER	4	\$ 265.00	+	
27	REAR SEAL RING	4	\$ 10.00	+	
28	REAR BUMPER WIRING SET	1	\$ 745.00	+	
29	REAR VENT TRIM	2	\$ 149.00	+	
30	REAR LID	1	\$ 3,497.00	+	
31	REAR LID LOCK	1	\$ 217.00	+	
32	REAR COVER CAP	1	\$ 8.00	+	
33	REAR LID ATTACHMENT PARTS	1	\$ 429.00	+	
34	REAR LID LOCK ACTUATOR	1	\$ 1,478.00	+	
35	REAR LOCK STRIKER	1	\$ 37.00	+	
36	REAR GASKET FOR FLAP	1	\$ 229.00	+	
37	REAR CLIP	2	\$ 4.00	+	
38	REAR PACKING ADHESIVE	1	\$ 21.00	+	
39	AUDI EMBLEM	1	\$ 144.00	✓	114.80
40	INSCRIPTION	1	\$ 104.00	✓	82.80
SUB TOTAL SPARE PARTS		:	\$ 8,532.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR EXHAUST TAIL PIPE TRIM - LH / RH <i>Dented</i>	2	\$	766.00	<i>✓</i> <i>8/12</i>
42	SUNDRIES ?		\$	500.00	<i>✓</i> <i>105-12</i>
43	REAR NO PLATE <i>HL m</i>		\$	60.00	<i>✓</i>
TOTAL SPARE PARTS		:	\$	21,152.00	
TOTAL LABOUR CHARGES		:	\$	8,332.00	
GRAND TOTAL		:	\$	29,484.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

CST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0595/2022/EQ
25-Jul-22
CHANG
1 of 1
SMP 4532 S
AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR BUMPER TRIM - LH/RH <i>Damaged</i> 2	\$ 90.00	✓ 70
GRAND TOTAL		\$ 90.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Resurveyed H.G.

*To add 1 day for the repairs
and spray painting to the
rear end panel.*

Adrian Ling
H.G.