

Acc. No. BA

REP

CC3/AIG 2006923/AC

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. 3103043781SG

Sum Insured: _____ Excess: \$550

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 4532S Yr Regn: 2019 / Sept

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1984

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 38299 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ2F41KA073898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35R19

R: 245/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 19/07/22

Survey held at Premises

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>00 AIG.</u>
<u>25/11</u>	<u>Confirmed final fig \$8,809.04 ; 5 days with Mr Boo. (Red 20,764.96, 70%)</u>
	<u>MV : 143K</u>
	<u>PV : 58.2K</u>
	<u>Nett: 84.8K</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

And Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Form: _____

☐ : Interview (\$ _____)

Photo: _____

☐ : Tech. Insp (\$ _____)

Others: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0595/2022/EQ
DATE : 18-Jul-22
WIP : 33439

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/07/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

11 days exclude 2 Sundays

Johnny Boo 21 Sep 22

OWNER'S NAME : MS PASCALE BOUCHARD CANNON
ADDRESS : 808A CHAI CHEE ROAD
#11-118
SINGAPORE 461808
TELEPHONE : HP +65 9178 3010
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900166583-01
VEHICLE NO : **SMP 4532 S**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 26/9/2019
ENGINE NO : CVK 081979
CHASSIS NO : WAUZZZF41KA073898
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jul-22
PLACE OF ACCIDENT : CLEMENCEAU & MERCHANT ROAD INTERSECTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 4532 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00		
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR BOTH REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$	3,000.00	\$	750.00
4	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS AND REAR END PANELLING.	\$	4,500.00	\$	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 8,332.00	\$	3,502.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
1	REAR BUMPER	1	\$	3,188.00	\$ 2,550.40
2	REAR BUMPER FIXING PARTS	1	\$	480.00	
3	REAR BUMPER SECURING STRIP	1	\$	249.00	\$ 198.80
4	REAR BUMPER SPOILER - LH / RH	1	\$	276.00	\$ 220.80
5	REAR BUMPER TRIM	1	\$	326.00	\$ 260.80
6	REAR BUMPER BRACKET - LH / RH	2	\$	260.00	\$ 208.00
7	REAR LIGHT REFLECTOR - LH / RH	2	\$	92.00	\$ 36.48
8	REAR LED LICENCE PLATE LIGHT	2	\$	209.00	
9	REAR LED TAIL LIGHT - LH / RH	2	\$	2,270.00	
10	REAR TRIM TAIL LIGHT - LH / RH	2	\$	68.00	
11	REAR LED TAIL LIGHT - LH / RH	2	\$	2,270.00	
12	REAR TRIM TAIL LIGHT - LH / RH	2	\$	68.00	
13	REAR BUMPER BEAM	1	\$	1,131.00	
14	REAR BUMPER SEAL	2	\$	32.00	
15	REAR BUMPER GUIDE SECTION - LH	1	\$	49.00	
16	REAR BUMPER GUIDE SECTION - RH	1	\$	51.00	
17	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	52.00	\$ 40.32
18	REAR PIN	2	\$	6.00	
19	REAR BUMPER HOLDING STRAP - LH / RH	2	\$	188.00	\$ 149.60
20	REAR RETAINER FOR AERIAL - LH	1	\$	29.00	
SUB TOTAL SPARE PARTS		:	\$	11,294.00	\$ 3,665.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	3,665.20
21	REAR TELEPHONE AERIAL	2	\$ 384.00		
22	REAR OPENING BOOT LID CONTROL UNIT	1	\$ 454.00		
23	REAR TAILGATE OPENING SENSOR LINE	1	\$ 228.00		
24	REAR BUMPER CONTROL UNIT RETAINER	1	\$ 9.00		
25	REAR BUMPER CROSS PANEL	1	\$ 120.00		
26	REAR SENSOR - INNER / OUTER	4	\$ 265.00		
27	REAR SEAL RING	4	\$ 10.00		
28	REAR BUMPER WIRING SET	1	\$ 745.00	\$	595.60
29	REAR VENT TRIM	2	\$ 149.00	\$	59.52
30	REAR LID	1	\$ 3,497.00		
31	REAR LID LOCK	1	\$ 217.00		
32	REAR COVER CAP	1	\$ 8.00		
33	REAR LID ATTACHMENT PARTS	1	\$ 429.00		
34	REAR LID LOCK ACTUATOR	1	\$ 1,478.00		
35	REAR LOCK STRIKER	1	\$ 37.00		
36	REAR GASKET FOR FLAP	1	\$ 229.00		
37	REAR CLIP	2	\$ 4.00		
38	REAR PACKING ADHESIVE	1	\$ 21.00		
39	AUDI EMBLEM	1	\$ 144.00	\$	114.80
40	INSCRIPTION	1	\$ 104.00	\$	82.80
SUB TOTAL SPARE PARTS		:	\$ 8,532.00	\$	4,517.92

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 4,517.92
41	REAR EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 766.00	\$ 612.00
43	ADDED PARTS - SEE ATTACHED		\$ 90.00	\$ 72.00
42	SUNDRIES		\$ 500.00	\$ 105.12
44	REAR NO PLATE		\$ 60.00	
TOTAL SPARE PARTS		:	\$ 21,242.00	\$ 5,307.04
TOTAL LABOUR CHARGES		:	\$ 8,332.00	\$ 3,502.00
GRAND TOTAL		:	\$ 29,574.00	\$ 8,809.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-19/08/22

**Supplementary Estimate-1**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0595/2022/EQ 25-Jul-22 CHANG 1 of 1 SMP 4532 S AUDI A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR BUMPER TRIM - LH/RH 2	\$ 90.00	\$ 72.00
GRAND TOTAL		\$ 90.00	\$ 72.00

For Premium Automobiles Pte Ltd

Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 4532 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✗	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR BOTH REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 3,000.00	500 + 250 750 8/8
4	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS AND REAR END PANELLING.	\$ 4,500.00	1650 + 550 2200 8/8
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,332.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
1	REAR BUMPER <i>Def d</i>	1	\$	3,188.00	✓ 2550.40
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$	480.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	1	\$	249.00	✓ 198.80
4	REAR BUMPER SPOILER - LH / RH <i>ut</i>	1	\$	276.00	✓ 220.80
5	REAR BUMPER TRIM <i>Def d</i>	1	\$	326.00	✓ 260.80
6	REAR BUMPER BRACKET (LH/RH) <i>Damaged</i>	2	\$	260.00	✓ 208.00
7	REAR LIGHT REFLECTOR - LH / RH <i>LH cracked</i>	2	\$	92.00	46.36.48
8	REAR LED LICENCE PLATE LIGHT <i>new</i>	2	\$	209.00	+
9	REAR LED TAIL LIGHT - LH (RH) <i>- outer.</i>	2	\$	2,270.00	+
10	REAR TRIM TAIL LIGHT - LH / RH <i>new</i>	2	\$	68.00	+
11	REAR LED TAIL LIGHT - LH / RH	2	\$	2,270.00	+
12	REAR TRIM TAIL LIGHT - LH / RH	2	\$	68.00	+
13	REAR BUMPER BEAM <i>new</i>	1	\$	1,131.00	+
14	REAR BUMPER SEAL	2	\$	32.00	+
15	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$	49.00	+
16	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$	51.00	+
17	REAR BUMPER GUIDE SECTION (LH/RH) <i>Damaged</i>	2	\$	52.00	✓ 40.30
18	REAR PIN <i>new</i>	2	\$	6.00	+
19	REAR BUMPER HOLDING STRAP (LH/RH) <i>cracked</i>	2	\$	188.00	✓ 149.60
20	REAR RETAINER FOR AERIAL - LH <i>Not new</i>	1	\$	29.00	+
SUB TOTAL SPARE PARTS		:	\$	11,294.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (O) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR TELEPHONE AERIAL	2	\$ 384.00	+	
22	REAR OPENING BOOT LID CONTROL UNIT	1	\$ 454.00	+	
23	REAR TAILGATE OPENING SENSOR LINE	1	\$ 228.00	+	
24	REAR BUMPER CONTROL UNIT RETAINER	1	\$ 9.00	+	
25	REAR BUMPER CROSS PANEL	1	\$ 120.00	+	
26	REAR SENSOR - INNER / OUTER	4	\$ 265.00	+	
27	REAR SEAL RING	4	\$ 10.00	+	
28	REAR BUMPER WIRING SET	1	\$ 745.00	+	
29	REAR VENT TRIM	2	\$ 149.00	+	
30	REAR LID	1	\$ 3,497.00	+	
31	REAR LID LOCK	1	\$ 217.00	+	
32	REAR COVER CAP	1	\$ 8.00	+	
33	REAR LID ATTACHMENT PARTS	1	\$ 429.00	+	
34	REAR LID LOCK ACTUATOR	1	\$ 1,478.00	+	
35	REAR LOCK STRIKER	1	\$ 37.00	+	
36	REAR GASKET FOR FLAP	1	\$ 229.00	+	
37	REAR CLIP	2	\$ 4.00	+	
38	REAR PACKING ADHESIVE	1	\$ 21.00	+	
39	AUDI EMBLEM	1	\$ 144.00	✓	114.80
40	INSCRIPTION	1	\$ 104.00	✓	82.80
SUB TOTAL SPARE PARTS		:	\$ 8,532.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 4532 S


S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	REAR EXHAUST TAIL PIPE TRIM - LH / RH <i>Dented</i>	2	\$ 766.00	<i>✓</i> <i>86.8</i> <i>612</i>
42	SUNDRIES ?		\$ 500.00	<i>✓</i> <i>105.12</i>
43	REAR NO PLATE <i>HL m</i>		\$ 60.00	<i>✓</i>
TOTAL SPARE PARTS		:	\$ 21,152.00	
TOTAL LABOUR CHARGES		:	\$ 8,332.00	
GRAND TOTAL		:	\$ 29,484.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0595/2022/EQ
25-Jul-22
CHANG
1 of 1
SMP 4532 S
AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR BUMPER TRIM - LH/RH <i>Damaged</i> 2	\$ 90.00	✓ 70
GRAND TOTAL		\$ 90.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Resurveyed H.S.

*To add 1 day for the repairs
and spray painting to the
rear end panel.*

Adrian Ling
H.S.