

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006933/ACY3M4**Date:** 11/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00147682100

Claimant Vehicle No : GBL5943J **Insured Vehicle No :** XE5117D

Date of Loss: 15/07/2022 Nature of Claim: TP Claim No: SNM22D204990/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL5943J**

Make & Model: PEUGEOT PARTNER, 1.5 BLUEHDI EAT8 LWB (A) Engine No: 10Q4DR0026115

Reg. Date: 29/10/2021 (Man. Year: 2020) Chassis No: VR3EFYHZRLJ907920

Colour: Silver Odometer: 17499 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,762.20	4,189.90	4,572.30	52.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,640.00	2,720.00	62.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,122.20	5,829.90	7,292.30	55.57
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	13,122.20	4,600.00	8,522.20	64.94

INSPECTION

Date of Assignment: 21/07/2022

Date Inspected: 21/07/2022 Inspected At: 39 DEFU LANE 12, SINGAPORE 539139
REPAIRER: ZOOM AUTOWERKS PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Oct 2022)	
Parts:	N/A	PEUGEOT PARTNER 1.5 BLUEHDI EAT8 LWB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5943J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	80.00 FL	*80.00 FL
2	1		*REAR TAILGATE -RH	Buckled	1,485.00 FL	*1,485.00 FL
3	1		*REAR TAILGATE OPENING RUBBER	Not Necessary	186.00 FL	*- FL
4	1		*REAR TAILGATE PEUGEOT EMBLEM	Necessary	58.00 FL	*58.00 FL
5	1		*REAR TAILLAMP -RH	Not Necessary	425.00 FL	*- FL
6	1		*REAR END PANEL	Not Necessary	685.00 FL	*- FL
7	1		*REAR BUMPER	Deformed	780.00 FL	*780.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	235.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER	Damaged	68.00 FL	*68.00 FL
10	1		*REAR FENDER -RH	Distorted	1,890.00 FL	*1,890.00 FL
11	1		*REAR SHOCK ABSORBER	Not Necessary	285.00 FL	*- FL
12	1		*REAR AXLE BEAM	Not Necessary	1,410.00 FL	*- FL
13	1		*REAR WHEEL BEARING	Not Necessary	321.00 FL	*- FL
14	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
15	1		*REAR TAILGATE 6PAX STICKER	Necessary	25.00 FS	*15.00 FS
16	1		*REAR TAILGATE SEALANT	Not Necessary	120.00 FS	*- FS
17	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
18	1		*REAR FENDER COMPANY STICKER	Necessary	450.00 FS	*180.00 FS
19	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
20	1		*REAR WHEEL RIM -RH	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,553.00	4,626.00
- List Item Discount on L Items 10.00/10.00% (\$)	790.80	436.10
Total Parts (\$)	8,762.20	4,189.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	60.00
8	TO APPLY UNDERCOATING	New	200.00	80.00
9	PANEL BEATING	New	1,600.00	700.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	600.00
Gross Labour Cost (S\$)			4,360.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >