



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
 #08-1339 Singapore 470130  
 Tel: 9450 7920  
 \* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

21 July 2022

REG NO.: GBL 5943 J  
 MAKE/MODEL: PEUGEOT PARTNER

Acknowledged by Repairer  
 Signature:

*TP Chin*  
*Celine*

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>new</i>	\$ 80.00 ✓
1	Rear tailgate -RH <i>Buckled</i>	\$ 1,485.00 ✓
1	Rear tailgate opening rubber <i>new</i>	\$ 186.00 +
1	Rear tailgate "PEUGEOT" emblem <i>new</i>	\$ 58.00 ✓
1	Rear taillamp -RH <i>new</i>	\$ 425.00 X
1	Rear end panel <i>new</i>	\$ 685.00 X
1	Rear bumper <i>dehnd</i>	\$ 780.00 ✓
1	Rear bumper reinforcement <i>new</i>	\$ 235.00 X
1	Rear bumper side retainer <i>new</i>	\$ 68.00 ✓
1	Rear fender -RH <i>Distorted</i>	\$ 1,890.00 ✓
1	Rear shock absorber <i>new</i>	\$ 285.00 X
1	Rear axle beam <i>new</i>	\$ 1,410.00 X
1	Rear wheel bearing <i>new</i>	\$ 321.00 X
		\$ 7,908.00
	Less 10%	\$ 790.80
		\$ 7,117.20

*4361*  
*3924.90*

### SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>new</i>	\$ 120.00 <i>40</i>
1	Rear tailgate "6PAX" sticker <i>new</i>	\$ -25.00 <i>15</i>
1	Rear tailgate sealant <i>new</i>	\$ 120.00 X
1	Rear bumper clip (1 set) <i>new</i>	\$ -80.00 <i>30</i>
1	Rear fender company sticker <i>new</i>	\$ -450.00 <i>180</i>
1	Rear tyre <i>new</i>	\$ 400.00 X
1	Rear wheel rim -RH <i>new</i>	\$ 450.00 X
		\$ 1,645.00

*265*

### LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring. <i>1640</i>	\$ 80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$ 150.00 <i>60</i>
3	To remove and refit rear reverse sensor.	\$ 120.00 <i>50</i>
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 80.00 <i>60</i>
5	To remove and refit rear undercarriage.	\$ 300.00 X
6	To conduct wheel alignment.	\$ 150.00 X
7	To remove and refit rear windscreen glass.	\$ 180.00 <i>60</i>
8	To apply undercoating.	\$ 200.00 <i>80</i>
9	Panel beating.	\$ 1,600.00 <i>700</i>
10	To re-spray painting on the affected areas.	\$ 1,500.00 <i>600</i>
		\$ 4,360.00

*Adrian G*  
*1/5. 06 Days*  
*Total: 582590*  
*1/5: 46K*

**GRAND TOTAL :**

**\$ 13,122.20**