

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 18/07/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLX7049X	MMBSTA13 AJH002059	
MODEL	: MITSUBISHI ATTRAGE 1.2		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 15-Jul-22
		TIME	: 08:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 1,080.50	\$ <u>1,080.50</u>
2	BOOTLID LOGO <i>new</i>	1	\$ 62.20	\$ 62.20
3	BOOTLID EMBLEM"ATTRAGE" <i>new</i>	1	\$ 63.00	\$ 63.00
4	BOOTLID EMBLEM"MIVEC TECHNOLOGY" <i>new</i>	1	\$ 63.00	\$ 63.00
5	BOOTLID EMBLEM"C&C" <i>new</i>	1	\$ 63.00	\$ 63.00
6	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 228.40	\$ 228.40
7	BOOTLID CATCH <i>new</i>	1	\$ 103.00	\$ 103.00
8	BOOTLID HINGE <i>new</i>	2	\$ 123.20	\$ 246.40
9	BOOTLID KEYLESS ANTENNA <i>new cracked</i>	1	\$ 233.20	\$ <u>233.20</u>
10	BOOTLID BUZZER <i>new cracked</i>	1	\$ 203.40	\$ <u>203.40</u>
11	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 230.00	\$ 230.00
12	REAR BUMPER <i>Distorted</i>	1	\$ 822.30	\$ 822.30
13	REAR BUMPER SIDE RETAINER <i>LH Dmg</i>	2	\$ 72.50	\$ 145.00
14	REAR BUMPER AIR VENT <i>cracked</i>	1	\$ 89.00	\$ 89.00
15	REAR BUMPER AIR VENT COVER <i>cracked</i>	1	\$ 133.00	\$ 133.00
16	REAR BUMPER REFLECTOR <i>cracked</i>	1	\$ 90.00	\$ 90.00
17	REAR BUMPER INNER SIDE BRACKET <i>new</i>	2	\$ 130.00	\$ 260.00
18	TAILLAMP LH <i>cracked</i>	1	\$ 530.00	\$ <u>530.00</u>

19	TAILLAMP PANEL LH <i>Dented</i>	1	\$ 190.00	\$ 190.00	<i>2</i>
20	REAR FENDER LH <i>Buckled</i>	1	\$ 890.00	\$ 890.00	<i>✓</i>
21	REAR FENDER INNER TRIM LH <i>Not nec</i>	1	\$ 420.00	\$ 420.00	<i>+</i>
22	REAR WINDSCREEN MOULDING <i>Nec</i>	1	\$ 155.00	\$ 155.00	<i>✓</i>
23	REAR END PANEL <i>Dented</i>	1	\$ 670.00	\$ 670.00	<i>2</i> <i>482</i>
24	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 174.00	\$ 174.00	<i>2</i>

4934.60
4441.14

TOTAL PRICE \$ 7,144.40
LESS 10% \$ 714.44
SUB TOTAL PRICE \$ 6,429.96

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not nec</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>Nec</i>	1	\$ 22.00	\$ 22.00
3	REAR BUMPER LOWER LID ASSY <i>cracked</i>	1	\$ 1,500.00	\$ 1,500.00
4	TAILLAMP CLIP (SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
5	TAILLAMP PANEL SEALANT <i>Nec</i>	1	\$ 20.00	\$ 20.00
6	REAR WINDSCREEN SEALANT <i>Nec</i>	1	\$ 120.00	\$ 120.00
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
8	REAR END PANEL INSULATION SEAL <i>Nec</i>	1	\$ 120.00	\$ 120.00
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 2,092.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>1300</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>1100</i>	
3	TUFF COAT	\$ 150.00	<i>80</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50</i>	
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 120.00	<i>50</i>	
7	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 100.00	<i>✓</i>	
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>	

TOTAL \$4,760.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,521.96
TOTAL LABOUR COST : \$ 4,760.00
TOTAL REPAIR COST : \$ 13,281.96

2710

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King.
L/s 18/07/22.

08 Days.

Total: 8493.14

L/s: 6.8K.

6-81C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: