

TP Chim.
Rehas.
GBE 5970 S. 2016 Jan.
Toyota Hiace. 2982 CC.
JT FHT02P000186439.

Rees Bumper	Behind	481.80. ✓
Rees Bumper Side Holder RH.	new	48.90 ✓
Taillap RH.	cut	306.10. ✓
Taillap lower Apcon RH.	Rejs	98.90 +
Rees RH Body Panel.	Dented	1867.80. ✓
Rees RH Body Panel Advertisement sticker.	new	180(SN)
Sliding Door Guide Rail RH.	x4	275.60 +
Sliding Door Guide Rail End Piece RH.	behind	85.20. ✓

2655.70

1991.70

S.N. 180

GBE59705.

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To remove upholstery.

To spray tuff coat

~~1005.~~ 700

~~600~~ 400

~~50~~ 30

~~100~~ 50

~~150~~ 50 1320

~~150~~ 80

total: 3491.77

H/S: 2.8K.

05 hrs.

2,800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: