

TSL Auto Garage

TIP Sampo
Veron.

Estimate

PAGE : 1/2

YEAR : 2018 VEHICLE NO : SMC560E
MODEL : HONDA FIT 1.3GF CVT CHASSIS NO : GK31316495

Third Party Claims

S/NO	ITEMS	Qty	Price
1	FRONT DOOR RH <i>Dented</i>	1	\$1,600.00
2	FRONT DOOR OUTER GLASS MOULDING RH <i>new</i>	1	\$330.00 <i>x</i>
3	FRONT DOOR OUTER STICKER "BLACK" RH <i>new</i>	1	\$110.00 <i>50 (sw)</i>
4	FRONT DOOR OUTER HANDLE WITH LOCK SENSOR <i>new</i>	1	\$490.00 <i>155</i>
5	FRONT DOOR OUTER HANDLE CAP RH <i>new</i>	1	\$90.00 <i>x</i>
6	FRONT DOOR LOCK RH <i>new</i>	1	\$520.00 <i>285</i>
7	FRONT DOOR INNER TRIM BOARD RH <i>new</i>	1	\$690.00 <i>355 466</i>
8	FRONT DOOR GLASS REGULATOR RH <i>new</i>	1	\$490.00 <i>228</i>
9	FRONT DOOR GLASS REGULATOR MOTOR RH <i>new</i>	1	\$290.00 <i>x</i>
10	FRONT DOOR HINGE RH <i>new</i>	2	\$440.00 <i>+</i>
11	FRONT DOOR INNER WEATHERSHIP RH <i>new</i>	1	\$320.00 <i>+</i>
12	REAR DOOR RH <i>Dented</i>	1	\$1,420.00 <i>981</i>
13	REAR DOOR OUTER GLASS MOULDING RH <i>new</i>	1	\$290.00 <i>+</i>
14	REAR DOOR OUTER STICKER "BLACK" RH <i>new</i>	1	\$90.00 <i>50 (sw)</i>
15	REAR DOOR OUTER HANDLE RH	1	\$290.00 <i>+</i>
16	REAR DOOR OUTER HANDLE CAP RH	1	\$60.00 <i>+</i>
17	REAR DOOR LOCK RH	1	\$490.00 <i>+</i>
18	REAR DOOR INNER TRIM BOARD RH	1	\$590.00 <i>+</i>
19	REAR DOOR GLASS REGULATOR RH	1	\$490.00 <i>+</i>
20	REAR DOOR GLASS REGULATOR MOTOR RH	1	\$290.00 <i>+</i>
21	REAR DOOR INNER WEATHERSHIP RH	1	\$290.00 <i>+</i>
22	REAR DOOR INNER CENTER WEATHERSHIP RH	1	\$110.00 <i>+</i>

2855 SN:100

2284

	Discount 20%	\$1,974.00
	TOTAL :	\$7,896.00

S/NO	SPECIAL ITEMS	Qty	Price
1	FRONT DOOR INNER TRIM CLIPS <i>new</i>	1	\$50.00 <i>30</i>
2	REAR DOOR INNER TRIM CLIPS <i>new</i>	1	\$50.00 <i>+</i>
3	DOOR VISOR <i>new</i>	1	\$100.00 <i>+</i>
			\$200.00
		Parts Total :	\$7,896.00
		S/P Item :	\$200.00
		TOTAL :	\$8,096.00

30

TSL Auto Garage

Estimate

PAGE : 2/2

YEAR : 2018 VEHICLE NO : SMC560E
MODEL : HONDA FIT 1.3GF CVT CHASSIS NO : GK31316495

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat front and rear frame members, to cut/weld and remove and refit above parts.	\$ 2,000.00
2	To putty, re-spray painting and polish front and rear affected areas.	\$ 2,000.00
3	To rust proof affected areas.	\$ 200.00
4	To remove and refit upholstery, seats, garnish, inner trimming boards.	\$ 200.00
5	To check and rectify wiring.	\$ 100.00
6	To remove and refit front and rear door assy.	\$ 300.00
7	To conduct diagnostic systems and to clear faults code.	\$ 300.00
8	To remove and refit front and rear door glass assy.	\$ 300.00

Adrian 16/9/22

~~500~~ 400

50

30

+

30

80

+

80

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

1220

TOTAL : \$ 5,400.00
PARTS TOTAL : \$ 8,096.00
GRAND TOTAL : \$ 13,496.00

Adrian L

1/s 03/08/22

04 Days.

Total 3834

1/s: 2.9K.

2.9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: