

TP Chim.

SMS1450Z.

Veron.

Toyota Siesta. 1496cc

NSP1707206889.

Reas	Number Plate	Best	30(SN) ✓
Reas	Number Plate Holder	Behind	30(SN) ✓
Reas	Number Plate Lamp x02	MP new	79 x 2 = 158 +
Reas	Bumper.	Distorted	678.10 ✓
Reas	Bumper Clips.	new	30(SN) ✓
Reas	Bumper Side Holder x02	Behind	70.5 x 2 = 141 ✓
Reas	Bumper Reflector x02	MP new	80.5 x 2 = 161 +
Reas	Bumper Centre Pad	2 Behind	225.40 ✓
Reas	Bumper Side Pad x02	1 Behind	127.5 x 2 = 255 ✓
Reverse	Sensor	Demaged	280(SN) 200(SN)
Reas	End Panel Outer	Distorted	689.50 ✓
Reas	End Panel Inner		433.80 ✓
Reas	End Panel Top Garnish.	Behind	155.20 ✓
Reas	End Panel Top Garnish Clips.	2 new	20(SN) ✓
Reas	End Panel Sealant.		60(SN) ✓
Reas	End Panel Antenna Sensor	could	190.50 ✓
Tail	Lamp x02	could	450.1 x 2 = 900.20 ✓

SMS1450Z.

Taillamp Panel x 02	RA Dented	^{407.20} $407.2 \times 2 = 814.40$
Tailgate	Distorted	1245.10. ✓
Tailgate Lock	Jammed	372.90 ✓
Tailgate Weatherstripe.	lt	329.50. ✓
Tailgate Hinge x 02	} NHP Per	$86.5 \times 2 = 173$ ✗
Tailgate Dampers x 02		$280.1 \times 2 = 560.20$ ✗
Tailgate Outer Garnish.	Cracked	257.30 ✓
Tailgate Outer Garnish Clips.	NHP	20(SN) ✓
Tailgate Inner Trim Board.	NHP	287.10. ✗
Tailgate Inner Trim Board Clips.	NHP	20(SN). ✓
Tailgate Reflector x 02	Cracked	$385.1 \times 2 = 770.20$ ✓
Tailgate Wiper Motor	Damaged	581.70. ✓
Tailgate Wiper Arm.	lt	185.80. ✓
Tailgate Wiper Arm Cover.	lt	24.10. ✓

SMS1450Z.

Tailgate Glass	Shattered	1251.40 ✓
Tailgate Glass Moulding	} Nee	130.20 ✓
Tailgate Glass Sealant.		60(SN) ✓
Tailgate Glass Solar Film.		200(SN) 280(SN)
Toyota Logo.	Nee	75.30 ✓
Rees Fender Inner Trim Board x 02	Deland	$699.1 \times 2 = 1398.20$
Rees Fender Inner Trim Board clips.	m	60(SN) ✓ 322.90
Rees Fender Outer Garnish. x 02	LH unke	$322.9 \times 2 = 645.80$
Rees Fender Outer Garnish clips.	m	60(SN) 20(SN)
Spare Tyre Panel.	Reis	1055.40. ✗
Spare Tyre Panel Top Board.	Deland	349.90. ✓
Spare Tyre Panel Sealant.	Nee m	60(SN) ✗
Rees Exhaust Pipe.	} Nee m	514.70. ✗
Rees Exhaust Pipe Mounting		35.90 ✗
Rees Exhaust Pipe Gasket		34.20 ✗

SMS 1450Z.

Rear Camera.

Damaged

~~380(SN)~~
~~480(SN)~~

Rear Video Recorder. Dmgd

~~580(SN)~~ 450(SN)

S.N: 1580

11410.40

Len 25%: 8557.80

Panel Beating
Spray Painting.

total: 12857.80

L/S: 10.2K.

08 Days.

Wiring.

To spray buff coat

To remove reuse sensors

To remove rear camera

To remove rear video recorder

To remove upholstery and rear seat.

To transfer tailgate fittings.

To replace tailgate glass.

To vacuum glass shards.

To remove exhaust pipe.

Towing Fees.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:

~~1500~~ 1000

~~1400~~ 1000

~~100~~ 30

~~150~~ 100

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~350~~ 100

~~150~~ 80

~~180~~ 120

~~120~~ 80

150 +

60. ✓

2720