

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OH CHEE BENG
BLK 29 TAMPINES CENTRAL 7 #04-0440
SINGAPORE 528612

Contact : 81393475

Te Chian.
Celine.

TAX INVOICE

Repair Code : CLM17295

Date in : 20/07/2022

Vehicle Num. : SLH4554H

Model : TOYOTA SIENNA 1.5X CVT

Chassis/Eng# : NSP1707009231/2NR8537344

C/T

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER Deformed	1	750.00	678 ✓ 750.00
REAR BUMPER CENTER PROTECTOR GARNISH Deformed	1	207.00	✓ 207.00
REAR BUMPER REFLECTOR L/R He new	2	85.00	x 170.00
REAR BUMPER SIDE END SEAL COVER L/R He new	2	81.00	x 162.00
REAR BUMPER SIDE PROTECTOR GARNISH L/R Deformed	2	151.00	✓ 302.00
REAR BUMPER SIDE RETAINER L/R 3x top new	2	90.00	x 180.00
REAR BUMPER TOW HOOK COVER	1	25.00	x 25.00
REAR END INNER PANEL Repair	1	696.30	x 696.30
REAR END OUTER PANEL Dented.	1	433.60	✓ 433.60
REAR END PANEL KEY ANTENNA SENSOR Cracked	1	127.00	✓ 127.00
REAR END PANEL TOP GARNISH Deformed	1	207.00	✓ 207.00
REAR FENDER INNER TRIM BOARD L/R RH cracked.	2	709.00	709. ✓ 1,418.00
REAR LUGGAGE COMPARTMENT TRAY Deformed	1	423.10	✓ 423.10
REAR LUGGAGE COMPARTMENT TRAY TOP COVER Deformed	1	255.60	✓ 255.60
REAR TAILGATE Dented.	1	1131.90	✓ 1,131.90
REAR TAILGATE 'LOGO' EMBLEM New	1	79.40	✓ 79.40
REAR TAILGATE INNER PULL HANDLE He new	1	38.00	x 38.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R Not new	2	19.00	x 38.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OH CHEE BENG
BLK 29 TAMPINES CENTRAL 7 #04-0440
SINGAPORE 528612

Contact : 81393475

TAX INVOICE

Repair Code : CLM17295

Date in : 20/07/2022

Vehicle Num. : SLH4554H

Model : TOYOTA SIENTA 1.5X CVT

Chassis/Eng# : NSP1707009231/2NR8537344

REAR TAILGATE INNER TRIM BOARD	<i>not rec</i>	1	208.00	<i>x</i>	208.00
REAR TAILGATE MECHANISM LOCK	<i>Dem'd</i>	1	265.00	<i>✓</i>	265.00
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>not rec</i>	2	68.00	<i>x</i>	136.00
REAR TAILGATE OUTER GARNISH	<i>lit.</i>	1	229.40	<i>✓</i>	229.40
REAR TAILGATE OUTER OPENER SENSOR	<i>not rec</i>	1	179.10	<i>x</i>	179.10
REAR TAILGATE REFLECTOR L/R	<i>not rec</i>	2	281.00	<i>+</i>	562.00
REAR TAILGATE WEATHER STRIP	<i>lit</i>	1	385.00	<i>✓</i>	385.00
REAR TAILGATE WINDSCREEN MOULDING L/R	<i>3 not</i>	2	45.00	<i>✓</i>	90.00
REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER)		2	45.00	<i>✓</i>	90.00
REAR TAILLAMP LOWER BRACKET L/R	<i>not rec</i>	2	83.10	<i>x</i>	166.20
Subtotal before discount					8,954.60
Percentage discount 25%					2,238.65
Sub-total 1					6,715.95
REAR BUMPER CLIPS - SET	<i>Not</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR	<i>Dem'd</i>	1	250.00	<i>200</i>	250.00
REAR END PANEL SEALANT	<i>Not</i>	1	100.00	<i>60</i>	100.00
REAR END PANEL TOP GARNISH CLIPS - SET	<i>Not</i>	1	30.00	<i>10</i>	30.00
REAR FENDER INNER SHIELD CLIPS L/R - SET	<i>not rec</i>	2	40.00	<i>x</i>	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OH CHEE BENG
BLK 29 TAMPINES CENTRAL 7 #04-0440
SINGAPORE 528612

Contact : 81393475

TAX INVOICE

Repair Code : CLM17295

Date in : 20/07/2022

Vehicle Num. : SLH4554H

Model : TOYOTA SIENTA 1.5X CVT

Chassis/Eng# : NSP1707009231/2NR8537344

REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	30	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	80.00	X	80.00
REAR TAILGATE NUMBER PLATE	1	25.00	X	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	X	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	10	30.00
REAR TAILGATE REVERSE CAMERA <i>new</i>	1	600.00	X	600.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	X	60.00
Subtotal before discount				1,515.00
Percentage discount 0%				0.00
Sub-total 2				1,515.00
Parts-total				8,230.95

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	60.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	800	1,500.00
To remove and reinstall exhaust pipe.	X	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800	1,400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OH CHEE BENG
BLK 29 TAMPINES CENTRAL 7 #04-0440
SINGAPORE 528612

Contact : 81393475

TAX INVOICE

Repair Code : CLM17295
Date in : 20/07/2022
Vehicle Num. : SLH4554H
Model : TOYOTA SIENTA 1.5X CVT
Chassis/Eng# : NSP1707009231/2NR8537344

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

1980 60 100.00
80.00
Labour Total 3,530.00
Parts & Labour Total 11,760.95

*** This is a computer-generated document which requires no signature.***

page 4

Adrian Ling -
L/S 06 Days.

total: 6589.75
L/S: S.2K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: